ATC Report No. B-94400/7CR-23 Contract No. N00019-76-C-0288



FRACTURE AND FATIGUE OF DIFFUSION, EXPLOSIVE, AND ROLL BONDED AI/AI AND TI/AI LAMINATES

R. D. GocIsby

Vought Corporation Advanced Technology Center Dallas, Texas 75222



13 May 1977

Final Report for Period 17 February 1976 - 17 February 1977

Approved for public release; distribution unlimited

Prepared for:

Department of the Navy Naval Air Systems Command Washington, D.C. 20361





B-94400/7CR-23 4. TITLE (and Subjute). Fracture and Fatigue of Diffusion, Explosive, and Roll Bonded AI/AI and TI/AI Laminates, and TC -B-94486/7CR-23 7. AUTHOR(s) R. D. Goolsby 8. PERFORMING ORGANIZATION NAME AND ADDRESS Vought Corporation Advanced Technology Center, inc. P. O. Box 6144 Dallar, Texas 75222 11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 12. MONITORING ACCEPT MAME AS ADDRESS(II dillerent from Controlling Office) 13. MECURITY CLASS, for the Controlling Office) Approved for public release; distribution unlimited. 16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) 18. KEY WORDS (Continue on reverse side if necessary and identify by block number) Metal laminates Fracture toughness Diffusion bonding Total 1-4V Fatigue crack propagation characteristics of TI/AI laminates were evaluated. Seven laminate panels of approxim. 12.7 mm (0.50 in.) thickness were fabricated using diffusion, explosi roll bonding procedures. Specific alloyed and roll bonded 7475 AI/1904, explosive bonded and followed by 100 bonded 74, explosive bonded and roll bonded 74, 12, 17, 17, 19, 19, 19, 19, 19, 19, 19, 19, 19, 19	B-94400/7CR-23 Tritle (and Subility) Tracture and Fatigue of Diffusion, Explosive, and Roll Bonded AI/AI and Ti/AI Laminates. AUTHOX(s) R. D. Goolsby Trepromise organization Name and address of the substitution of the Navy and I allar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75224 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75225 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75226 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75226 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of the Navy and I allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of Texas 1 all allar, Texas 75227 CONTROLLING OFFICE NAME AND ADDRESS of Texas 1 all allar, Texas 1 a	. REPORT NUMBER	PAGE	READ INSTRUCTIONS BEFORE COMPLETING F
Fracture and Fatigue of Diffusion, Explosive, and Roll Bonded Al/Al and TI/Al Laminates. 7. Author(s) 8. Performing organization hame and address: Yought Corporation Advanced Technology Center, Inc. 9. O. Sox 6144 Dallar, Texas 75222 11. Controlling office name and address: Department of the Navy Naval Alr Systems Command Washington, D. C. 20361 13. Monitoring Address Albert Male and Address: Department of the Navy Naval Alr Systems Command Washington, D. C. 20361 14. Monitoring Address Male a Address: Unclassified 15. DECLASSIFICATION/DOWN 16. CISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) 18. KEY WORDS (Continue on reverse side is insucessary and identify by block number) Metal laminates Damage tolerance Fracture toughness Diffusion bonding 17. OISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) The fracture and fatigue crack propagation characteristics of Ti/Al laminates are even evaluated. Seven laminate panels of approximation in the fracture and fatigue crack propagation characteristics of Ti/Al laminates were evoluated. Seven laminate panels of approximation bonded and roll bonded 74,5 Al 1, explosive bonded and followed by propagation bonded and roll bonded 74,5 Al 1, explosive bonded and followed propagation characteristics of propagation bonded and roll bonded 74,5 Al 1, explosive bonded and followed propagation bonded and roll bonded 74,5 Al 1, explosive bonded and followed propagation bonded and roll bonded 74,5 Al 1, explosive bonded and rol	FREEDRICASSISTICATION/ODWNGS CISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) EXECUTE (Continue on reverse aids if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of a continue on reverse aids if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of a continue on reverse aids if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of a continue on reverse aids if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of a continue on reverse aids if necessary and identify by block n		2. GOVT ACCESSION NO	3. MECTRIENT'S CATALOG NUMBE
Fracture and Fatigue of Diffusion, Explosive and Roll Bonded Al/Al and Ti/Al Laminates. ATC -B-94486/7CR-23 T. AUTHOR(s) R. D./Goolsby R.	racture and fatigue of Diffusion, Explosive, nd Roll Bonded Al/Al and Ti/Al Laminates. AUTHOR(s) R. D./Goolsby R. D./Goolsb	B-94400//CK-23		
and Roll Bonded Al/Al and Ti/Al Laminates and All Al and Al	ATTHOR(s) R. D. Goolsby PERFORMING ORGANIZATION NAME AND ADDRESS Ought Corporation Advanced Technology Center, Inc. O. Box 6144 All allar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS epartment of the Navy aval Air Systems Command lashington, D. C. 20361 MONITORING AGGIEVY MALE, A ADDRESS(if different from Controlling Office) ADDRESS(if different from Controlling Office) DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse side if necessary and identify by block number) Tracture toughness Diffusion bonding Ti-6A1-4V attigue crack propagation Explosive bonding ADDRESS(Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of if a laminates were evaluated. Seven laminate panels of approximation in the fracture and fatigue crack propagation characteristics of if All laminates were evaluated. Seven laminate panels of approximation in the control of	. TITLE (and Subtitle)	A CONTRACTOR OF THE PARTY OF TH	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A T C - B-94486/7CR-23 7. AUTHOR(s) R. D. Goolsby 8. PERFORMING ORGANIZATION NAME AND ADDRESS Vought Corporation Advanced Technology Center, Inc. P. O. Box 6144 Dallar, Texas 75222 11. CONTROLING OFFICE NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 14. Monitoring Acquest MAME, a Address(if different from Controlling Office) 15. SECURITY CLASS, of this is Unclassified 16. CISTRIBUTION STATEMENT (of the obstract entered in Block 20, 11 different from Report) Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 17. Distribution on reverse aids if necessary and identify by block number) Metal laminates Practure toughness Diffusion bonding 17. Total Continue on reverse aids if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of TI/Al laminates were evaluated. Seven laminate panels of approximation in the fracture and fatigue crack propagation characteristics of TI/Al laminates were evaluated. Seven laminate panels of approximation bonding procedures. Specific alloy systems investigated include diffusion bonding procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7455 Al/long vive bonded and roll bonded 7455 Al/long Al/Revenue and vive vive vive vive vive vive vive viv	ATT C - B-94466/7/CR-23 R. D. Goolsby R. D. Goolsby PERFORMING ORGANIZATION NAME AND ADDRESS Ought Corporation Advanced Technology Center, Inc. B. Box 6144 B. D. Goolsby PERFORMING ORGANIZATION NAME AND ADDRESS Ought Corporation Advanced Technology Center, Inc. B. Box 6144 B. D. Goolsby PERFORMING ORGANIZATION NAME AND ADDRESS OUGHT CORPORATION NAME AND ADDRESS OUGHT COLOR OFFICE NAME AND ADDRESS OUGHT COLOR OF NAME AND ADDRESS OUGHT COLOR OFFICE NA	Fracture and fatigue of Diffusion	, Explosive,	
R. D. Goolsby R. D.	R. D. Goolsby R. D.	and Roll Bonded Al/Al and Ti/Al L	aminates.	
R. D./Goolsby R. R. D./Goolsby R.	R. D. Goolsby R. D.	·	AT	
R. D. Goolsby 9. Serforming organization name and address Vought Corporation Advanced Technology Center, Inc. P. O. Box 6144 Dallar, Texas 75222 11. Controlling office name and Address Department of the Navy Naval Air Systems Command Washington, D. C. 20361 12. Monitoring Agginer Name and Education Controlling Office) 13. May 1977 14. Monitoring Agginer Name and Education Controlling Office) 16. CISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) 18. Supplementary Notes 19. KEY WORDS (Continue on reverse elder it necessary and identify by block number) Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 10. Ti-6Al-4V Fatigue crack propagation Explosive bonding 10. Address (Continue on reverse elder it necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximate of its bonding procedures. Specific alloy cystems investigated include diffusion bondeg and roll bonded 7475 Al/1100 Al, explosive bonded and r	R. D. Goolsby PERFORMING ORGANIZATION NAME AND ADDRESS Ought Corporation Advanced Technology Center, Inc. O. Box 6144 allar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS epartment of the Navy aval Air Systems Command ashington, D. C. 20361 MONITORING AGENEY NAME & ADDRESS(II dillerent from Controlling Office) DISTRIBUTION STATEMENT (of this Report) CISTRIBUTION STATEMENT (of the abstract entered in Block 20, II dillerent from Report) Supplementary Notes KEY WORDS (Continue on reverse side if necessary and identity by block number) Listribution condains Ti-6A1-4V Stracture toughness Diffusion bonding ADDRESS(II carried in propagation carried in controlling of the carried in bonding to the carried in carried in bonding to the carried in bonding to the carried in carrie	. AUTHOR(s)	(4) 11 1	
P. PERFORMING ORGANIZATION NAME AND ADDRESS Vought Corporation Advanced Technology Center, Inc. P. O. Box 6144 Dallar, Texas 75222 11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 12. MONITORING AGGIVEN MAME & ADDRESS(II dillerent from Controlling Office) Approved for public release; distribution unlimited. 16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) Metal laminates Dange tolerance P. O. Box 6144 13. May 1977 15. SECURITY CLASS. (of this in the interest from Controlling Office) 16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side it necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/A1 laminates were evaluated. Seven laminate panels of approximation in the fracture and fatigue crack propagation characteristics of Ti/A1 laminates were evaluated. Seven laminate panels of approximation in the control procedures. Specific alloy cystems investigated including roll bonding procedures. Specific alloy cystems investigated included if fusion bonded and roll bonded 7475 A1/1100 A1, explosive bonded and roll bonde	DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Supplementary Notes Exercised a reach and supplementary and identify by block number) Supplementary Notes Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) Exercised a reach and supplementary and identify by block number) The fracture and fatigue crack propagation characteristics of a supplementary and identify by block number) The fracture and fatigue crack propagation characteristics of a supplementary in the supplem	Contraction to the Contraction of the Contraction o		
Vought Corporation Advanced Technology Center, Inc. P. 0. Box 6144 Dallar, Texas 75222 11. Control-Ling Office Name and address Department of the Navy Naval Air Systems Command Washington, D. C. 20361 12. Monitoring Agenes Name & Address(if different from Controlling Office) 13. Security Class. (of this SCHEDULE CASSIFICATION/DOWN SCHEDULE) Approved for public release; distribution unlimited. 16. CISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) 18. SUPPLEMENYARY NOTES Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Crack arrest Roli bonding Ti-6Al-4V Fatigue crack propagation: Explosive bonding 10. ABSTRICT (Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation in the fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and full bonded 7475 Al/1100 Al, explosive bonded and full bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al	Ought Corporation Advanced Technology Center, Inc. O. Box 6144 Juliar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS epartment of the Navy Javal Air Systems Command Jashington, D. C. 20361 MONITORING AGENEW MANE & ADDRESS(II dillerent from Controlling Office) Includes Fire Monitoring AGENEW MANE & ADDRESS(II dillerent from Controlling Office) Opproved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse side it necessary and Identify by Disck number) ASSENCE (Continue on reverse side it necessary and Identify by Disck number) The fracture toughness Diffusion bonding Ti-6A1-4V Tatigue crack propagation Explosive bonding ASSENCE (Continue on reverse side it necessary and Identify by Mick number) The fracture and fatigue crack propagation characteristics of Michael Controlling of the Propaga	R. D./Goolsby	(1)	N00019-76-C-0288 N
Vought Corporation Advanced Technology Center, Inc. AREA & WORK UNIT NUMBE P. 0. Box 6144 Dallar, Texas 75222 11. Control-Ling Office NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 14. MONITORING AGENEY NAME & ADDRESS(II dillerent from Controlling Office) Approved for public release; distribution unlimited. 16. CISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) 18. SUPPLEMENTARY NOTES Metal laminates Practure toughness Diffusion bonding Crack arrest Fracture toughness Diffusion bonding Ti-6A1-4V Fatigue crack propagation: Explosive bonding Ti/Al laminates were evaluated. Seven laminate panels of approximation in the fractures and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation in the propagation procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and follioned 7475 Al/1100 Al, explosive bonded and follioned 7475 Al/1100 Al, explosive bonded and roll bonded	Ought Corporation Advanced Technology Center, Inc. O. Box 6144 Juliar, Texas 75222 CONTROLLING OFFICE NAME AND ADDRESS epartment of the Navy Javal Air Systems Command Jashington, D. C. 20361 MONITORING AGENEW MANE & ADDRESS(II dillerent from Controlling Office) Includes Fire Monitoring AGENEW MANE & ADDRESS(II dillerent from Controlling Office) Opproved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse side it necessary and Identify by Disck number) ASSENCE (Continue on reverse side it necessary and Identify by Disck number) The fracture toughness Diffusion bonding Ti-6A1-4V Tatigue crack propagation Explosive bonding ASSENCE (Continue on reverse side it necessary and Identify by Mick number) The fracture and fatigue crack propagation characteristics of Michael Controlling of the Propaga	PERFORMING ORGANIZATION NAME AND ADDRESS		
P. 0. Box 6144 Dallar, Texas 75222 I. CONTROLLING OFFICE NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 II. MONITORING AGENCY NAME & ADDRESS(II dillerent from Controlling Office) III. MONITORING AGENCY NAME & ADDRESS(II dillerent from Controlling Office) Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. III. DISTRIBUTION STATEMENT (of the abetract entered in Block 20, II different from Report) Metal laminates Fracture toughness Diffusion bonding Crack arrest Fatigue crack propagation Explosive bonding III. ABENING (Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of TI/Al laminates were evaluated. Seven laminate panels of approximation in the fracture of the fractures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 74	DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) Supplementary Notes Distribution statement (of the abstract entered in Block 20, If different from Report) Supplementary Notes Distribution statement (of the abstract entered in Block 20, If different from Report) Supplementary Notes NET WORDS (Continue on reverse elde if necessary and identify by block number) Supplementary Notes NET WORDS (Continue on reverse elde if necessary and identify by block number) The fracture toughness The fracture and fatigue crack propagation characteristics of attique crack propagation in the crack propagation characteristics of a control of the propagation on the crack propagation characteristics of a control of the propagation on the crack propagation characteristics of a control of the control of the propagation characteristics of a control of the propagation characteristics of a control of the control of th	= · · · · · · · · · · · · · · · · · · ·		
Dallar, Texas 75222 11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Navy Naval Air Systems Command Washington, D. C. 20361 10.7 13. May 1977 15. SECURITY CLASS. (of this in Unclass) field 16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Metal laminates Damage tolerance Fracture toughness Diffusion bonding Crack arrest Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of T1/A1 laminates were evaluated. Seven laminate panels of approximate. 12. 7 mm (0.50 in.) thickness were fabricated using diffusion, explosive bonding procedures. Specific alloy systems investigated include diffusion bonding procedures. Specific alloy systems investigated include diffusion bonding procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 A1/1100 A1, explosive bonded and	RETURNING OFFICE NAME AND ADDRESS (Language of the Navy aval Air Systems Command lashington, D. C. 20361 MONITORING AGENEW NAME & ADDRESS(II different from Controlling Office) Inclassified Is. DECLASSIFICATION/DOWNOR SCHEDULE CISTRIBUTION STATEMENT (of this Report) Improved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of this abstract entered in Block 20, II different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse side it necessary and identity by block number) Letal laminates Damage tolerance 7475 Al rack arrest Fracture toughness Diffusion bonding Ti-6Al-4V atigue crack propagation Explosive bonding ABSTRICT (Continue on reverse side if necessary and identity by block number) The fracture and fatigue crack propagation characteristics of identified in the control of the control o			
Department of the Navy Naval Air Systems Command Washington, D. C. 20361 13. Monitoning Adepare MAME & Address(il dillerent from Controlling Office) 15. SECURITY CLASS. (of this SCHEOULE 16. CISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the obstract entered in Block 20, If different from Report) Metal laminates Damage tolerance Fracture toughness Diffusion bonding Fatigue crack propagation Explosive bonding 10. ASSINCY (Continue on reverse side If necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately is not and in the propagation of the procedures. Specific alloy systems investigated include diffusion bonding procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll and the propagation characteristics of the propagation bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll and the propagation characteristics of the propagation bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll and the propagation characteristics and the propagation characteris	Repartment of the Navy aval Air Systems Command (ashington, D. C. 20361 MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY CLASS, (of this reposition of Inc. MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY CLASS, (of this reposition of Inc. MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, A ADDRESS(II dillerent from Controlling Office) MONITORING AGENCY NAME, ADDRESS(II dillerent f	· · · · · · · · · · · · · · · · · · ·	.	
Naval Air Systems Command Washington, D. C. 20361 10.7 114. MONITORING AGENEW NAME & ADDRESS(III dillerent from Controlling Office) 115. SECURITY CLASS. (of this included in the second of the sec	ASSIGNATION OF PAGES ASSIGNATION OF PAGES ASSIGNATION OF PAGES AND AGENCY NAME & ADDRESS(II different from Controlling Office) AND AGENCY NAME & ADDRESS(II different from Controlling Office) IS SECURITY CLASS, (of this report) Unclassified ISA. DECLASSIFICATION/DOWNOR CISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from Report) SUPPLEMENTARY NOTES Extracture toughness Damage tolerance 7475 Al Fracture toughness Diffusion bonding Ti-6Al-4V attigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of 1/Al laminates were evaluated. Seven laminate panels of approxima / 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded 7075 Al/71072 Al, and diffusion bonded 71-6Al-4V/6061 Al. A typic ponded 7075 Al/71072 Al, and diffusion bonded 74-6Al-4V/6061 Al. A typic ponded 7075 Al/71072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic		<i></i> ;	12. REPORT DATE
Naval Air Systems Command Washington, D. C. 20361 10. Monitoring Agenes Name & Address(it dillerent from Controlling Office) 11. Monitoring Agenes Name & Address(it dillerent from Controlling Office) 12. Security CLASS, rot this security CLASS	ASSINGUE AND CONTINUE ON CONTINUE ON CONTINUE OF PAGE ASSINGUE AND CONTINUE OF CONTINUE O	Department of the Navy	(//	13 May 1977
Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. Distribution STATEMENT (of the abstract entered in Block 20, if different from Report) Metal laminates Pamage tolerance 7475 Al Fracture toughness Crack arrest Fatigue crack propagation Explosive bonding Approximation and reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximate 12.7 mm (0.50 in.) thickness were fabricated using diffusion, explosi roll bonding procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded roll bonded roll parts to the control of the propagation of the control of the c	Unclassified Is. DECLASSIFICATION/DOWNGR CISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Supplementary notes KEY WORDS (Continue on reverse side if necessary and identify by block number) letai laminates Damage tolerance 7475 Alleracture toughness Diffusion bonding 7075 Alleracture toughness Roll bonding Ti-6Al-4V atigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Alleracture and fatigue crack propagation characteristics of Alleracture and fatigue crack propagation characteristics of Alleracture and Continue on reverse and Identify by block number) The fracture and fatigue crack propagation characteristics of Alleracture and Included Seven laminate panels of approximate y 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: lifefusion bonded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	Naval Air Systems Command		
Unclassified 15a. DECLASSIFICATION/DOWN SCHEDULE 15a. DECLASSIFICATION/DOWN SCHEDUL	Unclassified 15a. DECLASSIFICATION/DOWNER DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverce side it necessary and identify by block number) Retail laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Ratingue crack propagation Explosive bonding ABSTRICT (Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Al 17/Al laminates were evaluated. Seven laminate panels of approximation of the procedures. Specific alloy systems investigated included: 187 (17/6) 187 (187 (187 (187 (187 (187 (187 (187			
Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) B. KEY WORDS (Continue on reverse eldn it necessary and identify by block number) Metai laminates Damage tolerance 7475 Al Crack arrest Roli bonding 7075 Al Crack arrest Roli bonding TI-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of TI/Al laminates were evaluated. Seven laminate panels of approximated and folioning procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al, explosive bonded and reprosive bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al/110	DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Supplementary notes KEY WORDS (Continue on reverse side it necessary and identify by block number) letail aminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Track arrest Roli bonding Autique crack propagation Explosive bonding ADSTRICT (Continue on reverse side it necessary and identify by block number) The fracture and fatigue crack propagation characteristics of 1/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive oil bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and ponded 7075 Al/7672 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	4. MONITORING AGENCY NAME & ADDRESS(II dilleren	it from Controlling Office)	1 15. SECURITY GLASS. (of this repo
Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. Distribution statement (of the abstract entered in Block 20, if different from Report) Explosive from Report (of the abstract entered in Block 20, if different from Report) Metal laminates Damage tolerance Fracture toughness Diffusion bonding Ti-6A1-4V Fatigue crack propagation Explosive bonding Approximation (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al	EISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse elde if necessary and identify by block number) lettal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Fracture toughness Frack arrest Roli bonding ABSTRICT (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of 1/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: 101 iffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	127/1/b.		Unclassified
Approved for public release; distribution unlimited. Approved for public release; distribution unlimited. Distribution statement (of the abstract entered in Block 20, if different from Report) Explosion bonding for public release; and identify by block number; Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Crack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding Approved for public release; distribution unlimited. Approved for public release; distribution bonding 7075 Al Time for for public for public for provention of the fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation to bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 747	EISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse elde if necessary and identify by block number) lettal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Fracture toughness Frack arrest Roli bonding ABSTRICT (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of 1/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: 101 iffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic			154. DECLASSIFICATION/DOWNER
Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, il different from Report) 18. SUPPLEMENTARY NOTES 19. KEY WORCS (Coutinue on reverse elde li necessary and identify by block number) Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Crack arrest Roli bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding 10. ABSTRICT (Continue on reverse elde li necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation to bonding procedures. Specific alloy systems investigated included diffusion bonded and roli bonded 7475 Al/1100 Al, explosive bonded and	DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse elde 11 neueesery and identify by block number) letal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding Ti-6Al-4V atigue crack propagation Explosive bonding Ti-6Al-4V ASSENCET (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive collibonding procedures. Specific alloy systems investigated included inference and roll bonded 7475 Al/1100 Al, explosive bonded and conded 7075 Al/7672 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	/ •		SCHEDULE
Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, il different from Report) 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse elde li necessary and identify by block number) Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Crack arrest Roli bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding 10. ABSTRICT (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximation to bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al and the recommendation of the recomme	DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from Report) SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse elde 11 neueesery and identify by block number) letal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding Ti-6Al-4V atigue crack propagation Explosive bonding Ti-6Al-4V ASSENCET (Continue on reverse elde if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive collibonding procedures. Specific alloy systems investigated included inference and roll bonded 7475 Al/1100 Al, explosive bonded and conded 7075 Al/7672 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	6. DISTRIBUTION STATEMENT (of this Report)		
19. KEY WORDS (Continue on reverse elde li neueeeasy and identify by black number) Metai laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Crack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding 20. Assenct (Continue on reverse elde it neceesary and identify by block number) The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately. 7 mm (0.50 in.) thickness were fabricated using diffusion, explosive bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and	SUPPLEMENTARY NOTES KEY WORDS (Continue on reverse elde li neueeeery and identify by block number) letai laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Frack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding ABSENCT (Continue on reverse elde if neceeeery and identify by block number) The fracture and fatigue crack propagation characteristics of 1/Al laminates were evaluated. Seven laminate panels of approximately 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive folionating procedures. Specific alloy systems investigated included: Inffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and approach to the procedure of the proc			
Metal laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding Ti-6Al-4V The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately medical procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and	REY WORDS (Continue on reverse side it necessary and identity by block number) Retail laminates Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Frack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding ABOUNCY (Continue on reverse side it necessary and identity by block number) The fracture and fatigue crack propagation characteristics of Al I/Al laminates were evaluated. Seven laminate panels of approximally 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: Iiffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and sponded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	7. DISTRIBUTION STATEMENT (of the abstract entered	in Block 20, if different in	om Report)
Metal laminates Fracture toughness Crack arrest Fatigue crack propagation Explosive bonding Ti-6A1-4V Fatigue crack propagation The fracture and fatigue crack propagation characteristics of Ti/A1 laminates were evaluated. Seven laminate panels of approximately form (0.50 in.) thickness were fabricated using diffusion, explosional bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 A1/1100 A1, explosive bonded and roll bonded and rol	Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Frack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Al Ti/Al laminates were evaluated. Seven laminate panels of approximately approxima		in Block 20, il different in	on Report)
Metal laminates Fracture toughness Crack arrest Fatigue crack propagation Explosive bonding Ti-6A1-4V Explosive bonding The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately metals and included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded roll roll bonded roll bonded roll roll bonded roll bonded roll bonded roll bonded roll roll bonded roll roll roll roll roll roll roll rol	Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Frack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Al Ti/Al laminates were evaluated. Seven laminate panels of approximately approxima		in Block 20, ii different in	om Report)
Metal laminates Fracture toughness Crack arrest Fatigue crack propagation Explosive bonding Ti-6A1-4V Explosive bonding The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately metals and included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded roll roll bonded roll bonded roll roll bonded roll bonded roll bonded roll bonded roll roll bonded roll roll roll roll roll roll roll rol	Damage tolerance 7475 Al Fracture toughness Diffusion bonding 7075 Al Frack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Al Ti/Al laminates were evaluated. Seven laminate panels of approximately approxima		in Block 20, ii different in	an Report)
Fracture toughness Crack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately for more consistent of the procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded and rol	Track arrest Roll bonding 7075 Al Roll bonding Ti-6Al-4V atigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Al I laminates were evaluated. Seven laminate panels of approximately form (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic		in Block 20, ii different in	Sen Report) Report) Report)
Fracture toughness Crack arrest Roll bonding Ti-6Al-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately. The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately. The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately. The first panels of approximately form the following procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7475 Al/1100 Al/11	Track arrest Roll bonding 7075 Al Roll bonding Ti-6Al-4V atigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Al I laminates were evaluated. Seven laminate panels of approximately form (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	8. SUPPLEMENTARY NOTES		Of June
Crack arrest Roll bonding Ti-6A1-4V Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of Ti/A1 laminates were evaluated. Seven laminate panels of approximately minimum (0.50 in.) thickness were fabricated using diffusion, explosional bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 A1/1100 A1, explosive bonded and roll bonded A1/1100 A1, explosive bonded A1/1100	Ti-6A1-4V Tatigue crack propagation Explosive bonding ABSTRICT (Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	8. SUPPLEMENTARY NOTES 9. KEY WORDS (Cautinue on reverse side is necessary a	nd identify by black number	The sundant of the su
Fatigue crack propagation Explosive bonding The fracture and fatigue crack propagation characteristics of TI/Al laminates were evaluated. Seven laminate panels of approximately mm (0.50 in.) thickness were fabricated using diffusion, explosional bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and roll bonded and	The fracture and fatigue crack propagation characteristics of Alling (Continue on reverse side if necessary and identify by block number) The fracture and fatigue crack propagation characteristics of Alliaminates were evaluated. Seven laminate panels of approximally 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and conded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	8. SUPPLEMENTARY NOTES 9. KEY WORDS (Continue on toverse side in necessary or Metal laminates Damag	nd identify by block number ge tolerance	7475 A1
The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximal 12.7 mm (0.50 in.) thickness were fabricated using diffusion, explosional bonding procedures. Specific alloy systems investigated include diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and	The fracture and fatigue crack propagation characteristics of Ali/Al laminates were evaluated. Seven laminate panels of approximally 2.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and conded 7075 Al/7672 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	S. SUPPLEMENTARY NOTES S. KEY WORDS (Continue on reverse side in necessary or Metal laminates Damag Fracture toughness Diffu	nd identify by block number ge tolerance usion bonding	7475 A1 7075 A1
The fracture and fatigue crack propagation characteristics of Ti/Al laminates were evaluated. Seven laminate panels of approximately mm (0.50 in.) thickness were fabricated using diffusion, explosionable to bonding procedures. Specific alloy systems investigated included diffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded 7475 Al/1100 Al/1	The fracture and fatigue crack propagation characteristics of Alliaminates were evaluated. Seven laminate panels of approximal 12.7 mm (0.50 in.) thickness were fabricated using diffusion, explosive roll bonding procedures. Specific alloy systems investigated included: liffusion bonded and roll bonded 7475 Al/1100 Al, explosive bonded and sponded 7075 Al/7072 Al, and diffusion bonded Ti-6Al-4V/6061 Al. A typic	S. SUPPLEMENTARY NOTES S. KEY WORDS (Continue on reverse side in necessary at Metal laminates Damag Fracture toughness Diffu Crack arrest Roli	nd identify by block number ge tolerance usion bonding bonding	7475 A1 7075 A1
bonded 7075 A1/7072 A1, and diffusion bonded Ti-6A1-4V/6061 A1. A ty	aminate consisted of five 2.3 mm (0.090 in.) /4/5 Al primary layers	9. KEY WORDS (Continue on reverse elde li neueeemy at Metal laminates Damag Fracture toughness Diffu Crack arrest Roll Fatigue crack propagation Explo	nd identify by black number ge tolerance usion bonding bonding osive bonding	7475 A1 7075 A1 T1-6A1-4V

DD 1 JAN 73 1473

EDITION OF 1 NOV 55 (5 OBSOLETE 5/N 0102-014-6601 |

Unclassified

lata Entered

LECTRITY CLASSIFICATION OF THIS PAGE(When Date Entered)

20. Abstract

京都の東京をもまたことをもしいるというかの大変な、変しいないと

interleaved with four 0.13 mm (0.005 in.) 1100 Al secondary layers. It was found that all laminates exhibited substantially higher critical fracture toughness in the crack divider orientation than corresponding baseline, monolithic plate alloys. For example, the Al/Al laminates possessed average toughness values that ranged from 33% to 56% higher than those values for monolithic 7475 Al and 7075 Al plates. The Ti-6Al-4V/6061 Al panel had a toughness 117% higher than the baseline Ti-6Al-4V plate. Crack divider fatigue crack propagation rates were found to be similar to those rates for the baseline alloy plates. Crack arrest orientation fracture and fatigue propagation tests confirmed these laminates had significant crack arrest capacity. Criteria were outlined for afficient metal/metal laminate design for achieving highly damage tolerant structural materials.

Unclassified

PREFACE

This report describes the work performed at Vought Advanced Technology Center during the period 17 February 1976 to 17 February 1977 on a metals laminate development for structures program. This program was conducted for the Naval Air Systems Command under Contract No. N00019-76-C-0288. The project monitor was Mr. W. T. Highberger, Code AIR-52031D, Naval Air Systems Command, Washington, D. C.

The program was conducted under the supervision of Dr. D. H. Petersen. The principal investigator for this investigation was Dr. R. D. Goolsby. Technical support was provided by Messas. B. K. Austin, T. E. Mackie, J. H. Thomas, and W. M. Willis. Support for laminate fabrication was provided by: Mr. P. L. Mehr and Mr. A. N. Anderson, Alcoa Technical Center; Mr. h. E. Pattee and Mr. V. D. Linse, Battelle Columbus Laboratories; and Mr. J. F. Dolowy, Jr., DWA Composite Specialties, Inc.




TABLE OF CONTENTS

																										Page
PRE F	ACE					•							•					•								i
TABL	E OF (CONTENT	s.						•		•		•								•		•			ii
LIST	OF F	I GURES				•					•					•		•								iv
LIST	OF T	ABLES .							•												•			•		viii
1.0	INTR	ODUCT I OI	٧.			•								•	•											1
2.0	EXPE	RIMENTAI	L PRO	CEDU	JRE					•		•												•	•	3
	2.2	MATERIA LAMINA CHEMICA EVALUA	TE SE AL AN	LECT	TION	AN M I	D F Cro	AB ST	R I C RUC	TA: UT:	IRA)N \L	•	•	•	•	•	•	•	•	•	•	•	•	•	3 5 8
	2.4	MECHAN																								8
		2.4.1 2.4.2 2.4.3	Frac	ture	Te	sts					•	•									•	•	•		•	8 11 17
	2.5	FRACTO	GRAPH	IY .				•	•		L						•						•			18
3.0	RESU	LTS AND	DISC	ussı	ON					•	•		•					•								19
	3.1 3.2	CHARACT TITAN TENSILI LAMIN	IUM A E PRO	LLOY PERT	'S . TIES	AN	 D N	11 C	ROS	TR	NUC	Tu	RE	Ś	0 F	•										19 26
		3.2.1																								26
		3.2.2	Micr		uct	ura	1 0	ha	rac	te	rl	za	ti	on	0	f										36
	3.3	FRACTU	RE PR	OPER	T I E	s 0	FL	.AM	I N A	ΙΤΕ	F	AN.	EL	S		•						•				51
		3.3.1	Lam Frac	inat ture	es.	Ċr	ack	. A	rre	st		1e t	al	/M	le t	al	•								•	51 77
	a 1.	TAT LOU		ninat																						
	3.4	FATIGU															. 3	•	•	•	•	•	•	•	•	79
		3.4.1 3.4.2	Div	ı i de r	- Me	tal	/Me	ta	ĺL	.am	nir	at	es					•		•	•			•		79
		7.1.2		est.																_		_				87

TABLE OF CONTENTS (Continued)

																						Page
4.0	SUMMARY	AND	CON	ICLI	US	101	IS			•	•	•			•	•				•		97
REFE	RENCES .				•		•	•		•	٠	•	•	•				•	•		•	100
DIST	RIBUTION	LIST	Γ.																			103

LIST OF FIGURES

Figure	<u>Title</u>	Page
1.	Schematic of Metal/Metal Laminate Investigated.	6
2.	Schematic of Single-Sided Explosive Bonding Procedure for Fabrication of Laminate EAl.	9
3.	25.4 mm (1.00 in.) and 50.8 mm (2.00 in.) Gage Length Tensile Specimens.	10
4.	Compact Tension Fracture Specimen Used for Fracture Toughness and Fatigue Crack Propagation Testing.	12
5.	Single-Edge-Notched Fracture Specimen.	13
6.	Three Point Bend Fracture Specimen Used for Fracture Toughness and Fatigue Crack Propagation Testing.	14
7.	(a) Crack Arrest and (b) Crack Divider Laminate Orientations.	15
8.	Ultrasonic C-scan Record for a Portion of Diffusion Bonded 7475 Al/1100 Al Laminate DA2 Showing Unbonded Areas.	28
9.	Ultrasonic C-scan Record for a Portion of Roll Bonded 7475 Al/1100 Al Laminate RA4.	30
10.	Micrographs of Diffusion Bonded 7475 Al/1100 Al Laminates DA3 and DA2 Showing: (a) 1100 Al Interleaf in Laminate DA3; (b) 1100 Al Interleaf in Laminate DA2.	37
11.	Micrographs of Diffusion Bonded 7475 Al/1100 Al Laminate DAl Showing: (a) 1100 Al Interleaf; (b) 7475 Al/1100 Al Interface.	38
12.	Micrographs of Roll Bonded 7475 Al/1100 Al Laminate RA4 Showing: (a) 1100 Al Interleaf; (b) 1100 Al Interleaf.	39
13.	Micrographs of Roll Bonded 7475 Al/1100 Al Laminate RA4 Showing: (a) Debonded Areas at 7475 Al/1100 Al Interfaces Caused During Heat Treatment (Top 7475 Al Layer is an Outside Panel Layer); (b) 7475 Al/1100 Al Interface.	40
14.	Micrographs of Roll Bonded 7075 Al/7072 Al Laminate RAl Showing: (a) 7072 Al Interleaf; (b) 7075 Al/7072 Al Interface.	41
15.	Micrographs of Explosive Bonded 7075 Al/7072 Al Laminate EAl Showing: (a) 7072 A Interleaf; (b) 7075 Al/7072 Al Interface.	42

Figure	<u>Title</u>	Page
16.	Micrograph of Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI Showing 6061 Al Interleaf.	43
17.	Zn, Mg, and Cu Liffusion Profiles Across 0.13 mm (0.005 in.) 1100 Al Interleaf in Diffusion Bonded 7475 Al/1100 Al Laminate DA1 (Heat Treated to -T7651 Temper).	45
18.	Zn, Mg, and Cu Diffusion Profiles Across 0.13 mm (0.605 in.) 1100 Al Interleaf in Roll Bonded 7475 Al/1100 Al Laminate RA4 (Heat Treated to -T7651 Temper).	46
19.	Zn, Mg, and Cu Diffusion Profiles Across 0.13 mm (0.005 in.) 7072 Al Interleaf in Roll Bonded 7075 Al/7072 Al Laminate RAI (Heat Treated to -T7651 Temper).	47
20.	Zn, Mg, and Cu Diffusion Profiles Across 0.13 mm (0.005 in.) 7072 Al Interleaf in Explosive Bonded 7075 Al/7072 Al Laminate EAl (Heat Treated to have -T7651 Tensile Properties).	48
21.	Al and Ti Diffusion Profiles Across 0.10 mm (0.004 in.) 6061 Al Interleaf in Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI, Heat Treatment (Condition A): As Received [Mill Annealed + 1 hr. at 524°C (975°F)].	40
22.	Comparison of Zn Diffusion Profiles Across 1100 Al Interleaves of Different Thicknesses in 7475 Al/1100 Al Diffusion Bonded Laminates DA1, DA2, and DA3 (Heat Treated to -T7651 Temper).	50
23.	Comparison of Zn Diffusion Proliles Across 1100 Al Interleaves for 7475 Al/1100 Al Roll Bonded and Diffusion Bonded Laminates RA4 and DAI.	52
24.	Comparison of Zn Diffusion Profiles Across 7072 Al Interleaves for 7075 Al/7072 Al Roll Bonded and Explosive Bonded Laminates RAl and EAl.	53
25.	Failure Surfaces of Crack Divider SEN Specimens, Identified Left to Right: (a) Diffusion Bonded 7475 Al/1100 Al Laminates DA3, DA1, DA2; (b) Roll Bonded 7075 Al/7072 Al Laminate RA1, Roll Bonded and Diffusion Bonded 7475 Al/1100 Al Laminates RA4 and DA1.	64
26.	Failure Surfaces of Crack Divider SEN Fracture Specimens, Identified Left to Right: (a) Diffusion Bonded Ti-6A1-4V/6061 Al Laminate DTI, Monolithic Ti-6A!-4V; (b) Roll Bonded and Explosive Bonded 7075 A1/7072 Al Laminates RAI and EA1. Monolithic 7075 A1.	65

Figure	<u>Title</u>	Page
27.	Fractographs of Diffusion Bonded 7475 Al/1100 Al Laminate DAI SEN Failure Surface: (a) "Adhesive" Delamination at 1100 Al Interleaf; (b) 1100 Al "Adhesively-Failed Surface".	66
28.	Fractograph of Diffusion Bonded 7475 Al/1100 Al Laminate DA3 SEN Failure Surface Showing "Adhesive" Delamination of 1100 Al Interleaf from Adjacent 7475 Al Primary Layers.	67
29.	Fractographs of Roll Bonded Laminates RA1 and RA4 SEN Failure Surfaces: (a) "Cohesive" Failure in 7072 Al Interleaf in RA1; (b) "Adhesive" Delamination at 7475 Al/1100 Al Interface in RA4.	68
30.	Fractograph of Roll Bonded 7075 Al/7072 Al Laminate RAI SEN Failure Surface Showing Shear Lip Surfaces of 7075 Al Primary Layers and Dimpled Rupture Failure in 7072 Al Interleades (A) and (B) and "Adhesive" Delamination at (C).	69
31.	Fractographs of 7075 Al/7072 Al Roll Bonded (RAI) and Explosive Bonded (EAI) Laminates SEN Failure Surfaces Showing Dimpled Rupture Across 7072 Al Interleaves: (a) RAI; (b) EAI.	70
32.	Fractograph of Diffusion Bonded Ti-6Ai-4V/6061 Al Laminate DTI SEN Failure Surface Showing Development of Shear Lips in Adjacent Ti-6Ai-4V Layers.	71
33.	Transition in Failure Appearance from Flat Fracture for Thick Sections Under Plane Strain to Slant Fracture for Thin Sections Under Plane Stress.	73
34.	Comparison of Load/Crack-Opening-Displacement Fracture Toughness Test Results for Diffusion Bonded 77.75 Al/1100 Al Laminate DAl and Monolithic 7475-T7651 Al Plate, Crack Divider, L-T Orientations.	74
35.	Compa.ison of Load/Crack-Opening-Displacement Fracture Toughness Test Results for Diffusion Bonded Ti-6A1-4V/6061 Al Laminate DTI and Monolithic Ti-6A1-4V Plate, Crack Divider, L-T Orientations.	75
36.	Effect of Lamination on Crack Divider Fracture Toughness.	76
37.	Comparison of Load/Crack-Opening-Displacement Three Point Bend Fracture Test Results for Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DT! and Monolithic Ti-6Al-4V Plate, Crack Arrest, L-S Orientations.	80
38.	Three Point Bend Fracture Specimens for Diffusion Bonded 7475 Al/1100 Al Laminates DA1, DA2, DA3: (a) Crack Arrest at First 1100 Al Interleaf (DA3, DA1, DA2 Top to Bottom); (b) Crack Arrest in DA1 (Top) and DA2, but Delamination in Third 1100 Al Interleaf	Ωı

Figure	<u>Title</u>	Page
39.	Three Point Bend Fracture Specimens: (a) Explosive Bonded 7075 A1/7072 A1 Laminate EA1 Showing Crack Arrest at First 7072 A1 Interleaf; (b) Diffusion Bonded Ti-6A1-4V/6061 A1 Laminate DTI (Top) Showing Crack Arrest at First 6061 A1 Interleaf; Monolithic Ti-6A1-4V Plate Showing Total Failure.	82
40.	Fatigue Crack Propagation Rates for 11.9 mm (0.47 in.) Thick Roll Bonded Laminate RA4, Crack Divider, L-T Orientation.	83
41.	Fatigue Crack Propagation Rates for 2.3 mm (c. 90 in.) Thick 7475-T761 Al, L-T Orientation.	84
42:	Fatigue Crack Propagation Rates for 11.9 mm (0.47 in.) Thick 7475-T7651 Al, L-T Orientation.	85
43.	Comparison of Fatigue Crack Propagation Rates for Monolithic 7475-T761, -T7651 Al Sheet and Plate and Roll Bonded Laminate RA4, Crack Divider, L-T Orientation.	86
44.	Fatigue Crack Propagation Rates for 13.2 mm (0.52 in.) Thick Diffusion Bonded Laminate DTI, Crack Divider, L-T Orientation.	88
45.	Fatigue Crack Propagation Rates for 3.2 mm (0.12 in.) Thick Ti-6Al-4V, L-T Orientation.	89
46.	Fatigue Crack Propagation Rates for 13 7 mm (0.54 in.) Thick Ti-6A1-4V, L-T Orientation.	90
	Comparison of Fatigue Crack Propagation Rates for Monolithic Ti-6Al-4V Sheet and Plate and Diffusion Bonded Laminate DTI, Crack Divider, L-T Orientations.	91
48.	Fatigue Crack Propagation in 7475 Al/1100 Al Roll Bonded Laminate RA4, Crack Arrest, L-S Orientation, Three Point Bend Specimen, -T7651 Temper.	94
49.	Fatigue Crack Propagation in Ti-6Al-4V/6061 Al Diffusion Bonded Laminate DTI, Crack Arrest, L-S Orientation, Three Point Bend Specimen; Heat Treatment: Condition A.	95
	Three Point Bend Fatigue Crack Propagation Test Specimens: (a) Crack Arrest at First 1100 Al Interleaf in Roll Bonded 7475 Al/1100 Al Laminate RA4 (Top) and Complete Failure Under Fatigue for Monolithic 7475 Al (Bottom); (b) Same Observations Noted for (a) for Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI (Top) and Monolithic Ti-6Al-4V (Bottom).	3 6

LIST OF TABLES

Table	<u>Title</u>	Page
ì.	Baseline Aluminum and Titanium Alloy Sheets and Plates Investigated.	4
2.	Diffusion Bonded, Roll Bonded, and Explosive Bonded Al/Al and Ti/Al Laminate Panels Investigated.	7
3.	Chemical Analyses of Aluminum Alloys.	20
4.	Chemical Analyses of T:-6Al-4V Titanium Alloys.	21
5.	Tensile Properties of 7475 and 7075 Aluminum Sheet and Plate.	22
6.	Tensile Properties of Ti-6A1-4V Titanium Alloy Sheet and Plate.	23
7.	L-T Orientation Fracture Toughness Values of 7475 and 7075 Aluminum Sheet and Plate.	25
8.	L-T Orientation Fracture Taughness Values of Ti-6A1-4V Titanium Alloy Sheet and Plate.	27
9.	Tensile Properties of Diffusion Bonded 7475 Al/1100 Al Laminate Panels.	31
10.	Tensile Properties of Roll Bonded 7475 Al/1100 Al and 7075 Al/7072 Al Laminate Panels.	32
11.	Tensile Properties of Explosive Bonded 7075 A1/7072 Al Laminate EA1 Aged at 163°C (325°F).	34
12.	Tensile Properties of Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI.	35
13.	Crack Divider, L-T Orientation Fracture Toughness Values of Diffusion Bonded 7475 Al/1100 Al Laminate Panels.	54
14.	Crack Divider, L-T Orientation Fracture Toughness Values of Roll Bonded 7475 Al/1100 Al and 7075 Al/7072 Al Laminate Panels.	55
15.	Comparison of Average Critical Fracture Toughness Values (Crack Divider, L-T Orientation) for 7475 -T761 Al Sheet, Monolithic 7475 -T7651 Al Plate, and Diffusion Bonded and Roll Bonded 7475 Al/1100 Al Laminate Panels.	57

Table	<u>Title</u>	Page
16.	Crack Divider, L-T Orientation Fracture Toughness Values of Explosive Bonded 7075 A1/7072 A1 Laminate Panel EA1 Aged at 163°C (325°F) for 2.8 Hours.	58
17.	Comparison of Average Critical Fracture Toughness Values (Crack Divider, L-T Orientation) for 7075 -T76 Al Sheet, Monolithic 7075 -T7651 Al Plate, and Roll Bonded and Explosive Bonded 7075 Al/7072 Al Laminate Panels.	60
18.	Crack Divider, L-T Orientation Fracture Toughness Values of Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI.	61
19.	Comparison of Average Critical Fracture Toughness Values (Crack Divider, L-T Orientation) for Ti-6Al-4V Sheet and Monolithic Plate and Diffusion Bonded Ti-6Al-4V/6061 Al Laminate Panel DTI.	63
20.	Crack Arrest, L-S Orientation Three Point Bend Fracture Test Results for All Laminated Panels.	78
21.	Crack Arrest, L-S Orientation Three Point Bend Fatigue Crack Propagation Test Results for Roll Bonded 7475 Al/1100 Al Laminate RA4 and Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DT1.	93

1.0 INTRODUCTION

The application of metal laminates in structural design has seen an increased interest in the past few years, particularly in the aerospace field. Metal laminates are attractive as structural elements because they potentially offer greater reliability, increased life expectancy, and lower cost than conventionally forged and machined components. In particular, the high fracture and fatigue resistance and the crack arrest properties of metal laminates have been the subject of intense investigation. 1-21 These studies have included evaluations of metal/epoxy and metal/metal laminate panels, as well as structural component fabrications using laminated materials. Most of the studies related to aerospace applications have concerned metal/epoxy systems. These metal/epoxy systems have been concentrated on primarily because of the potential fabrication cost savings associated with these materials. However, metal/epoxy systems have been limited in primary aerospace structural applications because of uncertainties regarding their use in the presence of hostile environments (e.g. salt water) and their use at elevated temperatures. Thus, totally metallic laminate systems would be useful for structures operating under these more severe service conditions.

The present investigation is concerned with development of totally metallic laminates for aerospace structural application. In spite of the numerous studies that have been conducted in the past on both metal/epoxy and metal/metal laminates, insufficient information regarding material, configurational, and processing variables is available for efficient structural design using metal/metal laminates. This study is directed toward determining the effects of these various parameters on the fracture and fatigue properties of Al/Al and Ti/Al laminates. Seven different laminate configurations were fabricated by three distinctive processing methods: diffusion bonding, roll bonding, and explosive bonding. The materials systems were 7475 Al/1100 Al, 7075 Al/7072 Al, and Ti-6Al-4V/6061 Al. The specific experimental program conducted under this study was designed to isolate the following parameters affecting metal/metal laminate properties.

Laminate Properties vs. Sheet and Monolithic Plate Properties. For each of the seven metal/metal laminate configurations documented similar documentation was obtained for monolithic primary alloy

plate of the same thickness as the laminate panel. Also, properties were determined of primary alloy sheet of the same thickness as that of the primary layers in the metal/metal laminates.

<u>Process Method</u>. Diffusion bonding, roll bonding, and explosive bonding laminate fabrication methods were employed on identical Al/Al laminate configurations. This enabled direct comparisons to be made between the three fabrication methods regarding their effects on: metallurgical structure, tensile properties, fracture properties, and fatigue crack propagation properties of the processed laminates.

Alloy Type. 7075 Al and 7475 Al (both having very similar chemical compositions) were used as primary metals so that direct compositions could be made regarding the use of these two aluminum alloys in laminate materials. Titanium was also used as a primary laminate metal to evaluate its utility in laminate design.

Interleaf Thickness Effects. Three different interleaf thicknesses were employed in the fabrication of three laminates processed by the same method (diffusion bonding) and having the same metal/metal constitution (7475 Al/1100 Al). Test results from these three laminates allowed for comparison of metallurgical, tensile, fracture, and frigue crack propagation properties as a function of interleaf thickness.

The fracture and fatigue crack propagation behavior of these materials were characterized in both crack divider and crack arrest orientations. The metallurgical properties and failure mechanisms were documented using optical metallography, electron probe microanalysis, and scanning electron microscopy.

2.0 EXPERIMENTAL PROCEDURE

2.1 MATERIAL SELECTION

The essential first step in an experimental investigation of metal/metal laminates is the selection of primary and secondary laminae materials and thicknesses. From the numerous investigations that have been conducted on all types of laminar composite systems, it has been noted that the principal factors which affect the fracture resistance of laminates are:

- (1) Primary metal properties strength, toughness, ductility, etc.
- (2) Secondary (bonding or interleaf) metal strength, ductility bonding properties.
- (3) Primary metal lamina thickness
- (4) Secondary metal (interleaf) thickness

The selections of these metals are described below.

Primary Metal Selection. In the present investigation only aluminum and titanium alloys were considered for application as primary metals, because of the advantageous strength-to-weight ratios of these alloys. Selections of the exact aluminum and titanium alloys were based on fracture toughness vs. thickness characteristics, strength, fatigue resistance, corrosion resistance, and stress corrosion resistance. The alloys selected on this basis were 7075-T76, -T7651 Al; 7475-T761, -T7651 Al; and mill annealed Ti-6Al-4V titanium alloy. The baseline sheets and plates that were used in this investigation are given in Table 1.

Secondary (Bonding or Interleaf) Metal Selection. The secondary metal is considered important primarily because of its effect on bondline strength, and therefore on the tendency of the primary laminae to fail in a plane stress manner. Failure of the primary laminae under plate stress conditions is necessary to achieve maximum fracture toughness. For all three processing methods used in laminate preparation, a soft interleaf metal was employed as the secondary or bonding metal. 1100 Al was used as the interleaf metal in all Al/Al diffusion bonded panels and in one of the Al/Al roll bonded panels. 7072 Al was used as the secondary metal in the Al/Al explosive bonded panel and in one of the Al/Al roll bonded panel and in one of the Al/Al roll bonded panels. 6061 Al was used as the secondary metal in the diffusion bonded Ti/Al panel. Specific secondary metal thicknesses and laminate configurations are described in Section 2.2

TABLE 1. BASELINE ALUMINUM AND TITANIUM ALLOY SHEETS AND PLATES INVESTIGATED

			· · · · · · · · · · · · · · · · · · ·	
ALLOY	HEAT TREATMENT CONDITION	THE	MINAL' CKNESS' (In.)	LOT ON HEAT NUMBER
7475 A1	- T761	2.3	(0.090)	108 - 369
7475 AT	-T7651	13.2	(0.520)	
7075 A1	-т76	2.3	(0.090)	212251
7075 A1	-T7651	12.7	(0.500)	
Ti-6Al-4V Titanium	Mill Annealed	3.2	(0.125)	N6721
Ti-6Al-4V Titanium	Mill Annealed	13.7	(0.540)	N4555

2.2 LAMINATE SELECTION AND FABRICATION

Diffusion bonding, roll bonding, and explosive bonding were used to fabricate the Al/Al and Ti/Al laminate panels. Seven laminate panels were evaluated during this study: three diffusion bonded Al/Al laminates, two Al/Al roll bonded laminates, one Al/Al explosive bonded laminate, and one diffusion bonded Ti/Al laminate. The specific laminate configurations assessed (illustrated schematically in Figure 1) are detailed in Table 2 and are discussed in the following paragraphs.

Diffusion Bonded Laminate Panels. The diffusion bonded laminate panels were fabricated by DWA Composite Specialties, Inc. The Al/Al panels consisted of five layers of 2.3 mm (0.090 in.) thick 7475-T761 Al sheet interleaved with four layers of 1100 Al. The only differences among the three panels were the 1100 Al interleaf sheet thicknesses [0.05 mm (0.002 in.), 0.13 mm (0.005 in.), and 0.25 mm (0.010 in.)]. These panels were processed under vacuum for 1/2 hour at 477°C (830°F) at 20.7 MPa (3000 psi) pressure. The Ti/Al laminate consisted of four layers of 3.2 mm (0.125 in.) thick mill annealed Ti-6Al-4V titanium alloy sheet interleaved with three layers of 0.10 mm (0.004 in.) 6061 Al foil. This panel was processed under vacuum for 1/2 hour at 524°C (975°F) at 27.6 MPa (4000 psi) pressure. The area of all diffusion bonded panels fabricated was approximately 406 mm x 711 mm (16 in. x 28 in.).

Roll Bonded Laminate Panels. The roll bonded Al/Al laminate panels were fabricated and heat treated by Alcoa Technical Center. One laminate configuration (RAI) consisted of five layers of 2.3 mm (0.090 in.) 7075 Al sheet interleaved with four layers of 0.13 mm (0.005 in.) 7072 Al sheet. The other laminate configuration (RA4) consisted of five layers of 2.3 mm (0.090 in.) 7475 Al sheet interleaved with four layers of 0.13 mm (0.005 in.) 1100 Al sheet. Total size of laminate RAI was 11.9 mm x 305 mm x 1370 mm (0.47 in. x i2 in. x 54 in.). Total size of laminate RA4 was 11.9 mm x 305 mm x 1120 mm (0.47 in. x 12 in. x 44 in.). The final laminate panel was fabricated by initially processing three subpanels and warm rolling these three subpanels into the final configuration. After roll bonding the panels to final dimensions the laminates were heat treated to give -T7651 properties to the primary metal phase (7075 or 7475).




FIGURE 1. SCHEMATIC OF METAL/METAL LAMINATE INVESTIGATED.

TABLE 2. DIFFUSION BONDED, ROLL BONDED, AND EXPLOSIVE BONDED A1/A1 AND TI/A1 LAMINATE PANELS INVESTIGATED

Secretary to the secretary of the secret

			PRIMARY	METAL			Secondary Metal	y Meta		
LAMINATE PANEL DESIGNATION	BOND I NG PROCESS	ALLOY	NUMBER OF LAYERS	LAY	LAYER THICKNESS	ALLOY	NUMBER OR LAYERS	LAYER THICKNES	LAYER THICKNESS	NOMINAL LAMINATE PANEL SIZE
					(.u.)				(IL.)	('u')
DA)	Diffusion	7475 A1	5	2.3	(0.090)	1100 A1	†	0.13	(0.c05)	$11.9 \times 406 \times 711$ (0.47 × 16 × 28)
DA2	Diffusion	7475 A1	5	2.3	(0.090)	1100 A1	4	0.25	(0.010)	$12.4 \times 406 \times 711$ (0.49 × 16 × 28)
DA3	Diffusion	7475 A1	5	2.3	(0.090)	1100 A1	4	0.05	(0.002)	11.7 \times 406 \times 711 (0.46 \times 16 \times 28)
DTI	Diffusion	Ti-6Al- 4V	4	3.2	(0.125) 6061 AI	6061 A1	٣	0.10	(0.004)	13.2 × 406 × 711 (0.52 × 16 × 28)
RAI	Roll	7075 A1	5	2.3	(0.090) 7072 A1	7072 A1	†	0.13	0.13 (0.005)	11.9 × 305 × 1370 (0.47 × 12 × 54)
RAħ	Roll	7475 A1	2	2.3	(0.090)	1100 A1	4	0.13	0.13 (0.005)	11.9 × 305 × 1120 (0.47 × 12 × 44)
EAl	Explosive	7075 A1	5	2.4	(0.095) 7072 A1	7072 A1	4	0.13	0.13 (0.005)	$12.4 \times 279 \times 381$ (0.49 × 11 × 15)

Explosive Bonded Laminate Panel. The explosive bonded 7075 A1/7072 A1 laminate panel EAl was fabricated by Battelle Columbus Laboratories. This laminate was fabricated from five layers of 2.5 mm (0.099 in.) 7075-T6 Alclad Al sheet. Thus, the as-bonded laminate consisted of five layers of 2.4 mm (0.095 in.) 7075 Al interleaved with four layers of 0.13 mm (0.005 in.) 7072 Al sheet. Total area of the explosive bonded laminate was approximately 12.4 mm \times 279 mm \times 381 mm (0.49 in. \times 11 in. \times 15 in.). The laminate was fabricated using a single-sided welding procedure as illustrated in Figure 2. The standoff distances between the upper four sheets were all 1.52 mm (0.060 in.). The standoff distance between the lower two sheets was reduced to 1.02 mm (0.040 in.) to minimize any tendency toward overwelding. The panel was welded using SWP-1 explosive at a charge density of 1.65 g/cm². [SWP-1 explosive is a nitrostarch-sensitized ammonium nitrate powder explosive that detonates at a nominal velocity of 3000 m/sec (9850 ft/sec)]. Subsequent to fabrication the laminate was tempered at Vought Advanced Technology Center to give -T76 tensile properties to the 7075 Al.

2.3 CHEMICAL ANALYSIS, MICROSTRUCTURAL EVALUATION, AND NONDESTRUCTIVE INSPECTION

<u>Chemical Analysis</u>. All primary metal sheets and plates used in this program were analyzed to determine chemical compositions employing emission spectroscopy.

Microstructural Evaluation. Baseline metal sheets and plates and laminated panels were examined using a Leitz Ortholux metallograph. Electron probe microanalysis was performed on all laminated panels using a Cameca MF 46 analyzer.

Nondestructive Inspection. All laminated panels were inspected using ultrasonic C-scan.

2.4 MECHANICAL TESTING

2.4. Tension Tests

The tension tests were performed using the 25.4 mm (1.00 in.) and 50.8 mm (2.00 in.) gage length specimens shown in Figure 3. All materials were evaluated using the 50.8 mm specimen with the exception only of the explosive bonded laminate EAI. Triplicate tests were performed on all





FIGURE 2. SCHEMATIC OF SINGLE-SIDED EXPLOSIVE BONDING PROCEDURE FOR FABRICATION OF LAMINATE EAI.



SPECIMEN GAGE				Δ	DIMENSION mm (in.)				
	∢	æ	ပ	Q	m	Ŀ	9	Œ	-
	82.6 (3.25)	19.0	9.5	31.8 (1.25)	6.4 (0.25)	3.2 (0.12)	19.0	9.5	6.4 (0.25)
f	18 ⁴ (7.25)	50.8 (2.00)	25.4 (1.00)	57.2 (2.25)	12.7 (0.50)	12.7 (0.50)	38.1 (1.50)	19.0	12.7 (0.50)

25.4 mm (1.00 in.) AND 50.8 mm (2.00 in.) GAGE LENGTH TENSILE SPECIMENS FIGURE 3.

materials in the longitudinal orientation. These tests were run at 1.27 mm/min (0.05 in /min) at room temperature. Testing was accomplished on either a 90 kN (20 kip) capacity CGS or 450 kN (100 kip) capacity MTS servo-hydraulic closed-loop testing system under stroke control. Elongation was monitored using an MTS 632.12 strain gage extensometer.


2.4.2 Fracture Tests

Fracture toughness tests were performed using the compact tension (CT), single-edge-notched (SEN), and three point bend (TPB) specimens shown in Figures 4, 5, and 6. The SEN and CT specimens were used for all of L-T, crack divider orientation tests (Figure 7). The TPB specimen was used for L-S, crack arrest tests (Figure 7). Testing was performed in a manner similar to the ASTM E 399 test method for compact tension and three point bend specimens, 22 and to the procedures outlined in the Damage Tolerant Design Handbook. 23 The specimens were fatigue precracked at 10 Hz and subsequently tested to failure using a loading rate within the ASTM recommended range. A double cantilever crack-opening-displacement (COD) gage similar to that developed by Fisher, et al. 24 was used to monitor crack length during testing. Load and crack-opening-displacement were recorded on an X-Y recorder for all tests. These tests were run in triplicate at room temperature on either the CGS or MTS system described earlier.

Pertinent crack lengths relative to the load/crack-opening-displacement failure curves were determined using experimentally derived COD compliance calibrations. These COD compliance calibrations were determined for each specimen configuration (CT, SEN, and TPB, including a calibration for three different values of W for the TPB specimen).

The following fracture toughness parameters were determined for specimens tested in this study:

- K_Q conditional fracture toughness, determined by the 5% offset method described in ASTM E 399-74
- K apparent fracture toughness, evaluated using maximum failure load and the original crack length
 - K_c critical fracture toughness, evaluated using maximum failure load and the crack length at failure



- Notes: (1) Knife edges at notch opening are 5.1 mm (0.20 in.) apart.
 - (2) Notch is chevron shaped at tip and is 1.6 mm (0.063 in.) wide.
 - (3) a = 22.9 mm (0.90 in.) for fracture toughness
 test specimens.
 a = 10.2 mm (0.40 in.) for fatigue crack propagation
 test specimens.

FIGURE 4. COMPACT TENSION FRACTURE SPECIMEN USED FOR FRACTURE TOUGHNESS AND FATIGUE CRACK PROPAGATION TESTING.






FIGURE 5. SINGLE-EDGE-NOTCHED FRACTURE SPECIMEN.



- Notes: (1) W = 11.9 mm (0.47 in.), 12.7 mm (0.50 in.), 13.2 mm (0.52 in.) or 13.7 mm (0.54 in.),depending on plate thickness for each material tested.
 - (2) Crack-opening-displacement aluminum tabs were adhesively bonded to fracture toughness specimens. Tabs were 1.6 mm (0.062 in.) thick and were 5.1 mm (0.20 in.) apart.
 - (3) Notch was 0.8 mm (0.032 in.) wide and 1.3 mm (0.050 in.) deep.
- FIGURE 6. THREE POINT BEND FRACTURE SPECIMEN USED FOR FRACTURE TOUGHNESS AND FATIGUE CRACK PROPAGATION TESTING.






FIGURE 7. (a) CRACK ARREST AND
(b) CRACK DIVIDER LAMINATE ORIENTATIONS.

Compact Tension Fracture Specimen Stress-Intensity Determinations.

Fracture toughness values determined from compact tension specimen tests were calculated using the following relation 22 :

$$K = \frac{P}{RW^{1/2}} \qquad f(a/w) \tag{1}$$

where f(a/w) is given by:

$$f\left(\frac{a}{W}\right) = 29.6 \left(\frac{a}{W}\right)^{1/2} - 185.5 \left(\frac{a}{W}\right)^{3/2} + 655.7 \left(\frac{a}{W}\right)^{5/2} - 1017.0 \left(\frac{a}{W}\right)^{7/2} + 638.9 \left(\frac{a}{W}\right)^{9/2}$$

and

K - stress-intensity factor

P - load

B - specimen thickness

W - specimen width

a - specimen crack length

<u>Single-Edge-Notched Fracture Specimen Stress-Intensity Determinations.</u>
Fracture toughness values determined from SEN specimen tests were evaluated using the following expression²⁵:

$$K = \frac{Pa^{1/2}}{BW} \quad f(a/w) \tag{2}$$

where f(a/w) is given by:

$$f(a/W) = 1.99 - 0.41 \left(\frac{a}{W}\right) + 18.70 \left(\frac{a}{W}\right)^{2}$$
$$- 38.48 \left(\frac{a}{W}\right)^{3} + 53.85 \left(\frac{a}{W}\right)^{4}$$

and

K - stress-intensity factor

P - load

a - specimen crack length

B - specimen thickness

W - specimen width

Three Point Bend Fracture Specimen Stress-Intensity Determinations. Three point bend specimens used in this investigation had spanto-width ratios, S/W, of approximately 8. Fracture toughness values determined using TPB specimens were evaluated from the following expression 25,26

$$K = \frac{6Ma^{1/2}}{BW^2} \qquad f(a/W) \tag{3}$$

where f(a/W) is given by:

$$f(a/W) = 1.96 - 2.75 \left(\frac{a}{W}\right) + 13.66 \left(\frac{a}{W}\right)^2 - 23.98 \left(\frac{a}{W}\right)^3 + 25.22 \left(\frac{a}{W}\right)^4$$

and

K - stress-intensity factor

M - applied bending moment

a - specimen crack length

B - specimen thickness

W - specimen depth

2.4.3 Fatigue Tests

Fatigue crack propagation tests were performed using the L-T, crack divider orientation compact tension fracture specimen (Figure 4) and the L-S, crack arrest orientation three point bend fracture specimen (Figure 6). These tests were performed in a manner similar to the procedures recommended by the ASTM Task Group E24.04.01 on Fatigue Crack Growth Rate Testing. Tests were conducted on either the CGS or MTS closed-loop testing systems described in Section 2.4.1. These tests were conducted at room temperature at 10 Hz under load control. All tests were run at R = 0.1. Crack lengths were measured using a 40% traveling microscope. A minimum of three specimens were tested for each material to arrive at a final crack growth rate (da/dN) vs. stress-intensity factor range (Δ K) curve. Crack propagation rates were determined using the secant method. Stress-intensity factor ranges for

compact tension specimens were determined using the following expression: 20,29

$$\Delta K = \frac{\Delta P}{BW^{1/2}} \qquad f(\alpha) \tag{4}$$

where $f(\alpha)$ is given by:

$$f(\alpha) = \frac{(2 + \alpha)}{(1 - \alpha)^{3/2}} \left(0.866 + 4.64 \alpha - 13.32 \alpha^{2} + 14.72 \alpha^{3} \cdot 5.60 \alpha^{4}\right)$$

and:

ΔK - stress-intensity factor range

P - maximum load

P_{min} - minimum load

 α - a/W

a - specimen crack length

W - specimen width

B - specimen thickness

Stress-intensity factor ranges for three point bend specimens were determined using Equation 3, Section 2.4.2.

2.5 FRACTOGRAPHY

The fracture surfaces were examined using an optical metallograph and a Cambridge scanning electron microscope.

3.0 RESULTS AND DISCUSSION

3.1 CHARACTERIZATION OF BASELINE ALUMINUM AND TITANIUM ALLOYS

All primary sheet and monolithic plate alloys used in this investigation were characterized with respect to chemical composition, tensile properties, fracture properties and fatigue properties, so that direct comparisons could be made with properties of the laminated panels. For each of the seven laminates listed in Table 2, corresponding monolithic plate and sing layer sheet alloys were tested. For example, diffusion bonded 7475 Al/1100 Al laminates DAI, DA2, and DA3, made from 2.3 mm (0.090 in.) 7475-T761 Al sheet (Lot 108 - 369, Table 2), were compared with the 2.3 mm (0.090 in.) sheet and with 11.9 mm (0.47 in.) 7475-T7651 Al monolithic plate [machined from the 13.2 mm (0.52 in.) thick baseline plate]. The chemical analyses of all the principal aluminum and titanium alloys used in this investigation are given in Tables 3 and 4, respectively.

Tensile Properties. The tensile properties of the baseline 2.3 mm (0.090 in.) 7475-T761 Al and 7075-T76 Al sheet, 12.7 mm (0.500 in.) 7075-T7651 Al plate, and 13.2 mm (0.520 in.) 7475-T7651 Al plate are given in Table 5. These properties were determined using the 50.8 mm (2.00 in.) gage length tensile specimen configuration illustrated in Figure 3.

The tensile properties of the baseline 3.2 mm (0.125 in.) Ti-6A1-4V alloy sheet and 13.7 mm (0.540 in.) Ti-6A1-4V alloy plate are given in Table 6. The tensile properties shown were determined using the 50.8 mm (2.00 in.) gage length tensile specimen illustrated in Figure 3. Two heat treatment conditions were documented for these baseline Ti-6A1-4V materials:

Condition A - mill annealed + 1 hr at 524°C (975°F)

Condition B - mill annealed + 1 hr at 524°C (975°F) + 1 hr at 527°C (980°F), water quench, 18 hr at 160°C (320°F)

These two heat treatment conditions are comparable to those heat treatments given the laminated Ti-6Al-4V/6061 Al DTI panel. Condition A is the exact thermal treatment given to laminate DTI, since extra sheets of the 3.2 mm (0.125 in.) Ti-6Al-4V were included as baseline material in the diffusion bonding lay-up. Condition B includes a subsequent heat treatment given to some diffusion bonded laminate DTI material in order to increase the interleaf

TABLE 3. CHEMICAL ANALYSES OF ALUMINUM ALLOYS

Al	Bal.	Bal.	Bal.	Bal.	Bal.	Bal.	Bal.
Ξ	0.03	0.03	0.03	0.02	0.05	0.02	40.0
Zn	5.64	5.63	5.65	17.5	5.43	5.64	5.56
ن	0.22	0.20	0.20	0.20	0.21	0.20	0.20
Mg	2.33	2.57	2.34	2.74	2.47	2.62	2.44
£	0.00	0.00	00.0	50.0	50.0	0.03	60.03
n U	1.37	1.41	1,42	1.43	1.38	1.29	1.42
F.	0.08	0.06	90.0	0.24	0.24	0.21	0.24
:-	0.04	0.05	40.0	60.0	0.11	60.0	0.07
LOT NUMBER	108-369	356891		212251	356917	249231	
NOMINAL THICKNESS m (in.)	(060.0)	(0:090)	(0.520)	(060.0)	(060.0)	(660.0)	(0.500)
NOM	2.3	2.3	13.2	2.3	2.3	2.5	12.7
ALLOY	7475 Sheet	7475 Primary Roll Bonded Alloy	7475 Plate	7075 Sheet	7075 Primary Roll Bonded Alloy	7075 Alclad Sheet (Primary Metal)	7075 Plate

* Chemical analysis given in weight percent.

TABLE 4. CHEMICAL ANALYSES OF TI-6A1-4V TITANIUM ALIOYS

THE PROPERTY OF THE PROPERTY O

ALLOY	NOM I NAL THICKNESS	HEAT	ပ	n.	z	A	>	I	0	F
	mm (in.)		_							
Ti-6Al-4V Titanium Sheet	3.2 (0.125)	(0.125) N6721	0.022	0.11	0.022 0.11 0.018 6.4	6.4	4.0	4.0 0.004 0.14 Bal.	0.14	Bal.
Ti-6Al-4V Titanium Plate	13.7 (0.540)	N4555	0.022 0.16 0.010 6.2 4.2 0.009 0.19	0.16	0.010	6.2	4.2	0.009	0.19	Bal.

* Chemical analysis given in weight percent.

TABLE 5. TENSILE PROPerfies OF 7475 AND 7075 ALUMINUM SHEET AND PLATE

% REDUCTION OF AREA	29.2 36.6 26.7 avg. 30.8	29.8 42.1 41.3 avg. 37.7	20.9 22.3 <u>20.7</u> avg. 21.3	35.8 29.8 <u>29.0</u> avg. 31.5
\$ ELONGAT I ON	13.7 12.9 12.8 avg. 13.1	16.2 16.4 17.1 avg. 16.6	11.7 12.4 11.9 avg. 12.0	15.6 14.7 15.0 avg. 15.1
ATE IGTH (ksi)	(74.9) (74.3) (74.4) (74.5)	(75.8) (75.3) (75.9) (75.7)	(77.7) (78.4) (77.7) (77.9)	(77.0) (76.4) (77.0) (76.8)
ULTIMATE STRENGTH MPa (k	516 512 513 avg. 514	523 519 523 avg. 522	536 541 536 avg. 538	531 527 531 avg. 530
% RENGTH (ksi)	(68.2) (67.8) (67.8) (67.9)	(69.1) (68.3) (69.1)	(69.1) (69.9) (69.3) (69.4)	(69.6) (68.7) (69.5) (69.3) avg.
0.2% YIELD STRENGTH MPa (ksi	467 467 467 avg. 468	476 471 476 avg. 474	476 482 478 avg. 479	480 474 479 avg. 478
NOMINAL THICKNESS	(060.0)	(0.520)	(0.090)	(0.500)
NO THI	2.3	13.2	2.3	12.7
ALLOY AND TEMPER	7475-1761	7475-17651	7075-176	7075-17651

TENSILE PROPERTIES OF Ti-6A1-4V TITANIUM ALLOY SHEET AND PLATE TABLE 6.

% REDUCT 1 UN OF AREA	25.2 27.3 28.2 avg. 26.9	24.2 27.5 26.3 avg. 26.0	41.3 39.0 38.2 avg. 39.5
% ELONGATION	14.1 14.6 14.3 avg. 14.3	14.8 14.2 14.6 avg. 14.5	21.0 2:.3 20.5 avg. 20.9
ULTIMATE STRENGTH MPa (ksi)	986 (143) 979 (142) 972 (141) avg. 979 (142)	972 (141) 972 (141) 972 (141) avg. 972 (141)	965 (140) 979 (142) 986 (143) avg. 977 (142)
0.2% YIELD ŞTRENGTH MPa (ksi)	951 (138) 938 (136) 931 (135) avg. 940 (136)	938 (136) 938 (136) 938 (136) avg. 938 (136)	945 (137) 945 (137) 958 (139) avg. 949 (138)
NOMINAL THICKNESS	3.2 (0.125)	3.2 (0.125)	13.7 (0.540)
HEAT	CGNDITION A	CONDITION B	CONDITION A
ALLOY	Ti-6A1-4V Sheet	Ti-6Al-4V Sheet	Ti-6Al-4V Plate

* Condition A: mill annealed + 1 hr @ $524^{\circ}C$ (975°F).

^{@ 524°}C (975°F) + 1 hr @ 527°C (980°F), water quench, ** Condition B: mill annealed + 1 hr 18 hr @ 160°c (320°F).

(6061 Al) strength. Thus, Condition A baseline Ti-6Al-4V material was given the additional the mal processing for more direct comparability to the Condition B processed laminate DT1 material. Table 6 gives the tensile properties of the 3.2 mm (0.125 in.) sheet for both Condition A and B. As is evident from these test results the additional thermal processing to the Condition B state had no effect on the tensile properties of the Ti-6Al-4V sheet.

Fracture Toughness Properties. The L-T orientation fracture toughness values of the baseline 2.3 mm (0.090 in.) 7475-T761 A1 and 7075-T76 A1 sheet, 12.7 mm (0.500 in.) 7075-T7651 A1 plate, and 13.2 mm (0.520 in.) 7475-T7651 A1 plate are given in Table 7. Fracture tests on the 13.2 mm (0.520 in.) 7475-T7651 A1 plate were conducted on specimens with a thickness of 11.9 mm (0.470 in.), so that these specimens would be of the same dimensions as comparable 7475 A1/1100 A1 laminate specimens. The 38.1 mm (1.50 in.) wide single-edge-notched specimen (Figure 5) was used for all fracture tests with the exception only of the 11.9 mm (0.470 in.) thick 7475-T7651 A1 plate alloy, where additional compact tension (Figure 4) fracture tests were also conducted. Values of conditional fracture toughness (K_Q), apparent fracture toughness (K_Q), apparent fracture toughness (K_Q), and critical fracture toughness (K_Q) have all been tabulated in Table 7.

The fracture values of the sheet alloys given in Table 7 are not directly comparable to most fracture values listed in such references as the Damage Tolerant Design Handbook because of the small width of the specimens used for tests in this investigation. It was necessary to use small specimens in this program due to the limited quantities of laminate panel material available for testing. However, data for the 7475 Al and 7075 Al sheet does seem to compare well with data Wygonik determined for 86.2 mm (3.0 in.) wide fracture specimens. Complete KQ, Kapp, and Kc data for the thick 7475 Al and 7075 Al plates were not available for comparison. The results of Table 7 show that 7475 Al possesses significantly higher fracture toughness than 7075 Al, as has been noted previously. 30-32

Additional testing of the 7475 Al plate material was conducted using CT specimens, since these specimens were used for fatigue crack propagation tests, described in Section 3.4.1. As can be seen from Table 7 no significant differences were noted in he fracture toughness values for the SEN and CT specimen configurations.

TABLE 7. L-T ORIENTATION FRACTURE TOUGHNESS VALUES OF 7475 AND 7075 ALUMINUM SHEET AND PLATE

FRACTURE 55, K	(ksivin)	(77.8) (85.7) (82.4)	(82.0)	(60.5)	(60.8)	(60.3)	(:-)	(57.0)	(59.2)	(1.65)	(58.0)	(67.9)	(40.9) (37.0)	(42.2)	(70.0)
CRITICAL FRACTURE TOUGHNESS, K	mPa√m	85.5 94.2 90.6	avg.90.1	66.5 65.6	66.8	avg.66.3	:	62.6	avg.65.2	65.0	63.7	avg.63.7	£.04 6.44	4.94	8vg.44.0
APPARENT FRACTURE TOUGHNESS, App	(ksivin)	(59.0) (60.2) (58.2)	(5.4.1)	(25.7)	(54.5)	(54.3)	(52.4)	(52.4)	(52.5)	(48.5)	(46.1) (44.3)	(46.3)	(32.0)	(32.1)	(31.9)
APPARENT FRAC	MPavm	64.8 66.2 64.0	avg. 65.0	60.}	59.9	avg. 60.4	57.6	57.6	7.72 . gve	53.3	50.7	evg. 50.9	35.2	35.3	avg. 35.0
CONDITIONAL FRACTURE DUGHNESS, KQ	(ksl/in)	(35.1) (35.4) (32.7)	(34.4)	(47.3)	(48.5)	(4.7.6)	(45.8)	(44.1) (45.1)	(45.1)	(30.3)	(28.1)	-	(31.1)	(31.0)	(31.1)
CONDITION/ FRACTURI TOUGHNESS,	Mavm	38.6 38.9 35.9	avg. 37.8	52.0	53.3	avg. 52.4	50.3		. 6ve	33.3		avg.	34.2	34.1	avg. 34.2
MAX!MUM LOAD	(kips)	88 (2.22) 1 (2.28) 3 (2.31)		3 (9.97)		•	1	(3.24)			7 (1.74)		2 (5.43)		
£ ,) KN	9.68		44.3	_		-	4.41		┢	7.74		24.2		
5% JFFSET LOAD	(kips)	(1.32) (1.34) (1.30)		(8.62)				(2.73)		(01.10)			(5.27)		
2, 3	 - -	5.87 5.96 5.73		38.3	38.0		L	12.1		L_	4.72		23.4	24.7	
CRITICAL CRACK LENGTH	(in.)	8 (0.780) 5 (0.806) 0 (0.787)		8 (0.742)			()	2 (1.109)	•		3 (0.760)		9 (0.823)		
504)	1) 19.8 1) 20.5 2) 20.0		18.8		 ,	- -	28.2		5) 19.5			0) 20.9	6) 20.	
INITIAL CRACK LENGTH	(in.)	(0.681) (0.681) (0.662)		(0.706)	0.7		(1.074)	(1.059)	3	(0.69	(0.677)	3.0	(0.740)	(0.72	
Les and	men.	17.3 17.3 16.8		17.9	18.2		27.3	26.9	?	17.6	17.2	?:	18.8	18.4	
SPECIMEN		SEN			SEN			t	; 		SEN			25.1	
NOM!NAL THICKNESS	(in.)	2.3 (0.n90)					(0/4/0) 6-11				2.3 (0.090)		000	(0.500)	
NON	Į.	2.3				:	٠ <u>.</u>				2.3			1.7.	
ALLOY AND TEMPER		1475-1761					14/2-1/651				7075-176			(005.0) (.2) 159/1-5/0/	

*7475-77651 Al 11.9 mm (0.47 in.) thick specimens were machined from 13.2 mm: (0.52 ln.) plate.

ansEN - single-edge-notched fracture specimen; CT - compact tension fracture specimen.

The L-T orientation fracture properties of the baseline 3.2 mm (0.125 in.) Ti-6A-4V alloy sheet and 13.7 mm (0.540 in.) Ti-6Al-4V alloy plate are given in Table 8. K₀, K_{app}, and K_c values were determined for the sheet material in both Condition A and Condition B heat treatments. As would be expected, the additional heat treatment involved in Condition B heat treating (a solution treatment, water quench, and age for the 6061 Al interleaf in the DT! laminate) had no effect on the Ti-6Al-4V sheet fracture properties. Single-edge-notched fracture specimens were used for all tests except for additional compact tension tests included for the plate material. The CT tests were included because this specimen configuration was selected for fatigue crack propagation testing, described in Section 3.4.1. As was the case for the 7475 Al plate material, no differences in fracture toughness values were noted for tests conducted using either the SEN or CT specimen configurations.

Fatigue Crack Propagation Properties. Fatigue crack propagation tests of 2.3 mm (0.090 in.) 7475-T761 Al sheet, 11.9 mm (0.470 in.) 7475-T7651 Al plate, 3.2 mm (0.125 in.) Ti-6Al-4V alloy sheet, and 13.7 mm (0.540 in.) Ti-6Al-4V alloy plate were conducted using the compact tension specimen (Figure 4) and the three point bend specimen (Figure 6). The results of these tests are discussed in Section 3.4, where direct comparisons are made to similar tests on laminate panels.

3.2 TENSILE PROPERTIES AND MICROSTRUCTURES OF LAMINATE PANELS

3.2.1 Tensile Properties of Laminate Panels

Prior to sectioning and machining for tensile test specimens, each laminate panel was nondestructively inspected for unbonded areas using ultrasonic C-scan. The following observations were made relative to laminates fabricated by the three different lamination processes:

Diffusion Bonded Laminates - It was found that diffusion bonded 7475 Al/II00 Al laminates DA2 and DA3 showed several areas of poor bonding, as shown in Figure 8 for laminate DA2. The other diffusion bonded laminates (7475 Al/ II00 Al laminate DA1 and Ti-6A1-4V/6061 Al laminate DT1) showed no unbonded areas by C-scan inspection.

Roll Bonded Laminates - These laminates were characterized by surface blisters which appeared after heat treatment. The

TABLE 8. L-T ORIENTATION FRACTURE TOUGHNESS VALUES OF T;-6A1-4V TITANIUM ALLOY SHEET AND PLATE


However the second of the seco

	_			-								
CRITICAL FRACTURE TOUGHNESS, K	MPa/m (ksivin)	;) 158 (144) 152 (138)	avg.155 (141)	149 (136) 152 (138)	148 (135)	avg.150 (136)	(5.7 (59.8)	59.2 (53.9)	avg. 62.8 (57.1)	(1.25) 4.22	68.4 (62.2)	avg. 65.1 (59.2)
APPARENT FRACTURE TOUGHNESS, K	MPavm (ksivin)	95.2 (86.6) 99.9 (90.9) 95.8 (87.2)	avg.97.0 (88.2)	95.6 (87.0) 96.9 (88.2)		avg.95.9 (87.2)	(8.14) 6.24	42.6 (38.8)	avg.44.3 (40.3)	(9.04) 9.44		avg.47.6 (43.3)
CGND1710NAL FRACTURE TOUGHNESS, KQ	Mfarm (ksir/in)	61.2 (55.7) 58.8 (53.5) 59.6 (54.2)	avg. 59.9 (54.5)		52.1 (47.4)	avg. 53.2 (48.5)	44.6 (40.6)	41.5 (37.8)	avg. 42.8 (39.0)	42.3 (38.5)	49.2 (44.8)	avg. 45.3 (41.2)
MAX IPUM LOAD	kN (kips)	16.9 (3.81) 20.3 (4.57) 21.9 (4.92)		i	22.2 (5.00)		30.8 (6.92)			14.1 (3.17)		
5% OFFSET LOAD	kN (kips)	10.9 (2.45) 16.9 12.0 (2.69) 20.3 13.6 (3.06) 21.9		l .			29.9	32.2 (7.23) 33.0		13.3 (3.00) 14.1	15.4 (3.46)	
CRITICAL CRACK LENGTH	mm (33.)	21.6 (0.849) 22.0 (0.867) 21.0 (0.826)	**************************************	6.5 (0.648) 20.5 (0.808) 6.6 (0.652) 20.6 (0.812)	20.7 (0.816)		22.9 (0.903)	21.6 (0.849)		30.1 (1.186)	30.0 (1.182)	
INITIAL CRACK LENGTH	mm (in.)	19.2 (0.754) 18.0 (0.710) 16.9 (0.664)		16.5 (0.648) 16.6 (0.652)	16.7 (0.658)		19.8 (0.783)	18.7 (0.737) 2		25.6 (1.008)	25.8 (1.014)	
SPEC IMEN TYPE		SEM			SEN			SEN			ט	
HEAT TREATHENT		CONDITION A			CONDITION B				CONDITION A			
NOMINAL	mm (in.)		3.2 (0.125)						113.7 (0.540) CONDITION A			
ALLOY		V4-184-17	Titanium	Sheet				107.1				

» Condition A: Mill annealed + 1 hr \in 524°C (975°F).

Condition B: Mill annealed + 1 hr \$ 524°C (975°F) + 1 hr @ 527°C (980°F), water quench, 18 hr @ 160°C (320°F).

and SFN - single-edge-notched fracture specimen; CT - compact tension fracture specimen.



ULTRASONIC C-SCAN RECORD FOR A PORTION OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE DA2 SHOWING UNBONDED AREAS. FIGURE 8.

blisters were quite numerous over the area of the panels and were easily identified visually. Ultrasonic C-scan (Figure 9) and subsequent metallographic analysis confirmed that the unbonded areas occurred at the outside primary/secondary bondlines. Explosive Bonded Panel Ultrasonic C-scan inspection of explosive bonded laminate 7075 Al/7072 Al revealed no unbonded areas.

Tensile Properties of Diffusion Bonded 7475 Al/1100 Al Laminates.

The as-received diffusion bonded 7475 Al/IIOO Al laminates DAL, DA2, and DA3 were heat treated at Vo.ght Advanced Technology Center to achieve -T7651 tensile properties. These panels were heat treated according to the specifications of Alcoa 467 Process for 7475 Al sheet material. The primary 7475 Al layers comprising laminates DA1. DA2, and DA3 were cut from baseline sheet (Lot 108-369, Table 3) that had been processed to -T761 properties. Consequencly, after the laminate bonding process, these primary layers were essentially given a resolution treatment, water quench, and age cycle similar to what they had been subjected to previously, except that the laminate panels were strained approximately 2% after the quench stage to relieve quenching stresses. It was found that approximately 20% of the heat treatment specimen blanks delaminated along 7475 Al/1100 Al interfaces due to the severity of the water quench. This delamination was more prevalent in the laminate blanks with the thinnest 1100 Al interleaf [laminate DA3 with the 0.05 mm (0.002 in.) thick 1100 Al interleaf]. Very few delaminations were noted for laminate DA2, which had the thickest 1100 Al interleaf [0.25 mm (0.010 in.)]. The tensile properties of laminate panels DA1, DA2, and DA3 heat treated in the manner described above are shown in Table 9. All properties shown are typical of 7475 Al processed to the ~T7651 condition.

Tensile Properties of Roll Borded 7475 Al/1100 Al and 7075 Al/7072 Al Laminates. The roll bonded laminates RAl (7075 Al/7072 Al) and RA4 (7475 Al/1100 Al) were fabricated and heat treated to the -T7651 temper by Alcoa Technical Center. The tensile properties of these laminates are given in Table 10. All properties shown are representative of alloys 7075 and 7475 heat treated to the -T7651 temper.

Tensile Properties of Explosive Bonded 7075 Al/7072 Al Laminate EAL.

This laminate was fabricated by Battelle Columbus Laboratories using five layers




FIGURE 9. ULTRASONIC C-SCAN RECORD FOR A PORTION OF RCLL BONDED 7475 A1/1100 A1 RA4. (NOTE THE PRESENCE OF BOTH LARGE AND SMALL SURFACE BLISTERS.)

TABLE 9. TENSILE PROPERTIES OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE PANELS

を表現の関連のである。これでは、100mmのでは、100

LAMINATE PANEL DESIGNATION	SECONDARY ALLOY (1100 A1) LAYER THICKNESS	4DARY 1100 A1) 7ER (NESS	0.2% YIELD STRENGTH	2% FRENGTH	ULTIMATE STRENGTH	АТЕ GTH	& ELONGATION
	mm	(in.)	МРа	(ksi)	MPa	(ksi)	
DA1	0.13	(0.005)	95ti .	(66.2)	502	(77.8)	12.5
DA2	0.25	(0.010)	44.1 44.1 44.1 avg. 45.2	(64.0) (64.4) (64.0) (64.1)	485 489 487 avg. 487	(70.3) (70.9) (70.6) (70.6)	11.8 12.0 13.5 avg. 12.4
DA3	0.05	(0.002)	024	(68.2)	518	(75.1)	8

*Laminates were heat treated to give -17051 properties to the primary metal phase (7475 Al). ***Primary alloy (7475 Al) layers were nominally 2.3 mm (0.090 in.) thick. **Laminate panels were nominally 11.9 mm (0.47 in.) thick.

TABLE 10. TENSILE PROPERTIES OF ROLL BONDED 7475 A1/1100 A1 AND 7075 A1/7072 A1 LAMINATE PANELS

LAMINATE PANEL DESIGNATION	PRIMARY/ SECONDARY ALLOYS	0.2% Y		ULT:M STREN		% ELONGATION
		MPa	(ksi)	MPa	(ks!)	
		454	(65.9)	512	(74.2)	16.0
	! 7475 A1/	465	(67.4)	526	(76.3)	15.4
RA4	1100 A1	462	(67.0)	524	(76.0)	14.9
		avg. 460	(66.8)	avg. 521	(75.5)	avg. 15.4
		47C	(68.1)	534	(77.4)	12.8
	7075 A1/	4	(68.0)	537	(77.9)	13.5
RAI	7072 A1	474	(68.7)	536	(77.8)	13.6
		avg. 471	(68.3)	avg. 536	(77.7)	avg. 13.3

^{*} Laminates were heat treated to give -T7651 properties to the primary metal phase.

^{**} Laminate panels were nominally 11.9 mm (0.47 in.) thick.

^{***} Primary alloy layers were nominally 2.3 mm (0.090 in.) thick, while secondary alloy layers were nominally 0.13 mm (0.005 in.) thick.

of 2.4 mm (0.099 in.) 7075-T6 Alclad Al sheet. Upon receipt of this material from Battelle samples were tempered according to normal heat treatment specifications for achieving -T76 tensile properties from previously heat treated -T6 sheet. [A recommended temper would be: 16.5 hr at 163°C (325°F)]. It was found that aging in this manner caused extensive overaging in the laminate, with corresponding low strength levels. For example, the yield strength was only 369 MPa (53.5 ksi) instead of the more typical value of 469 MPa (68.0 ksi) for 7075-T7651. Subsequent tempering, microhardness, and tensile evaluations were made on laminate EAl to establish the appropriate aging time at 163°C (325°F) to achieve -T76 tensile properties. The tensile results of these evaluations are given in Table II. It was found that an aging time of 2.8 hr was sufficient to obtain -T76 tensile properties in explosive bonded 7075 Al/7072 Al laminate EAL. The extreme amount of energy characteristic o the explosive bonding process sufficiently altered the aging kinetics of the primary 7075 Al alloy to cause the drastically reduced aging time noted in Table II. All fracture specimens of laminate EAl, described in Section 3.3, were aged at 163°C (325°F) for 2.8 hr.

Tensile Properties of Diffusion Bonded Ti-6Al-4V/6061 Al Laminate DTI. The tensile properties of laminate DTI were determined under two heat treatment conditions as noted previously in Section 3.1. These conditions were:

- Condition A the as-received laminate panel. This was considered equivalent to Ti-6Al-4V sheet in the mill annealed state given a 1 hr soak at 524°C (975°F).
- Condition B this treatment consisted of as-received laminate DTl (Condition A) processed as follows: 1 hr at 527°C (980°F), water guenched, 18 hr at 160°C (320°F).

The Condition B treatment was used so that the 6061 Al interleaf strength could be increased to approach the -T6 temper for this alloy. Microhardness readings in the 6061 Al bondlines in laminate DTI confirmed the Condition B interleaf had a higher strength level. (Condition A 6061 Al had a Knoop microhardness of 61, while Condition B 6061 Al had a Knoop microhardness of 94). The tensile properties of diffusion bonded Ti-6Al-4V/6061 laminate DTI are given in Table 12. These values are slightly lower than the strength

TABLE 11. TENSILE PROPERTIES OF EXPLOSIVE BONDED 7075 A1/7072 A1 LAMINATE EA1 AGED AT 163°C (325°F)

AGING TIME AT 163°C (325°F)	O. YIELD S	2% TRENGTH		IMATE ENGTH	% ELONGATION
hr	MPa	(ksi)	MPa	(ksi)	
0.0	591	(85.7)	612	(88.8)	11.5
1.0	514	(74.5)	547	(79.4)	14.0
2.0	496	(71.9)	536	(77.7)	14.0
	476 485	(69.1) (70.3)	524 534	(76.0) (77.4)	13.5
2.8	456	(66.1)	516	(74.8)	15.4
	avg. 472	(68.5)	avg. 525	(76.1)	avg. 14.9
4.0	419	(60.8)	475	(68.9)	13.7
16.5	369	(53.5)	438	(63.5)	15.2

^{* 25.4} mm (1.0 in.) gage length tensile specimens were used for properties determinations.

^{**} Laminate panel EA1 was nominally 12.4 mm (0.49 in.) thick.

^{***} Primary alloy (7075 Al) layers were nominally 2.4 mm (0.095 in.) thick, while secondary alloy (7072 Al) layers were nominally 0 13 mm (0.005 in.) thick.

TABLE 12. TENSILE PROPERTIES OF DIFFUSION BONDED TI-6A1-4V/6061 A1 LAMINATE DT)

TORREST TO THE TORREST IN THE TABLE TO THE

ALTERIAL CONTROL OF THE PROPERTY OF THE PROPER

HEAT TREATMENT	6.2% YIELD STRENGTH MPa (k	ELD TH (ksi)	ULTIMATE STRENGTH MPa (IATE IGTH (ksi)	% ELONGATION
Condition A	924	(134)	965	(140)	19.3
	924	(134)	965	(140)	18.2
	924	(134)	965	(140)	18.2
	avg. 924	(134)	avg. 965	(140)	avg. 18.6
Condition B	931	(135)	965	(140)	16.4
	924	(134)	965	(140)	16.4
	924	(134)	965	(140)	17.0
	avg. 926	(134)	avg. 965	(140)	avg. 16.6

* Laminate panel DT1 was nominally 13.2 rm (0.52 in.) thick.

** Primary alloy (Ti-6Al-4V) layers were nominally 3.2 mm (0.125 in.) thick, while secondary alloy (6061 Al) layers were nominally 0.10 mm (0.004 in.) thick.


**** Condition B: as received plate [mill annealed + 1 hr @ 524° C (975°F)] + 1 hr @ 527° C (980°F), water quench, 18 hr @ 160° C (320°F). *** Condition A: as received plate [mill annealed + 1 hr @ 524°C (975°F)].

values noted in Table 6 for the 3.2 mm (0,125 in.) Ti-6A1-4V baseline sheet from which laminate DTI was made. The difference in values is attributed to the small volume fraction (approximately 2%) of lower strength 6061 A1 in laminate DTI. There were no detectable differences in the tensile properties of laminate DTI in the Condition A or B heat treat state.

3.2.2 Microstructural Characterization of Laminate Panels

The microstructures of the diffusion bonded, roll bonded, and explosive bonded laminates were evaluated using optical metallography and electron probe microanalysis. Micrographs illustrating the microstructures of all seven laminates are given on the following pages in Figures 10 through 16. The significant features regarding the microstructures of these laminates are discussed in the following paragraphs.

Diffusion Bonded and Roll Bonded Al/Al Laminate Microstructures. In examining the micrographs of diffusion bonded 7475 Al/1100 Al laminates DA3, DA2, and DA1 in Figures 10 and 11, it can be seen that there exists a discontinuous third phase at the 7475 Al/1100 Al interface. Similar observations were found regarding roll bonded 7475 Al/1100 Al laminate RA4 and roll bonded 7075 Al/7072 Al laminate RAI (Figures 12, 13, and 14). This phase was now definitely identified either by optical metallographic techniques or by electron probe microanalysis; however, it is likely that it is an oxide phase. As will be discussed at more length in Section 3.3, this phase had a direct effect on the failure mechanisms found in these laminates. It has already been noted in Section 3.2.1 that diffusion bonded laminates DA1, DA2, and DA3 all were subject to delamination along the 7475 Al/1100 Al bondlines during water guenching from the solution temperature during heat treatment. These decaminate as were observed always to be "adhesive" in nature (i.e., separation always occurred at the original interface between the 7475 Al and the 1100 Al and not within the soft 1100 Al phase). Similar "adhesive" delamination was at a noted for the roll bonded laminates RA1 and RA4, which developed surfa - listers during heat treatment. Figure 13 shows an example of such "adhesive" delamination at a surface blister in roll bonded 7475 Al/ 1100 Al laminate RA4. Although the "adhesive" bondline failures noted above have been attributed to the presence of a third phase at the Al/Al interface in these laminates, "adhesive" failure was not the only mode of failure noted for these materials. In fact roll bonded laminates RAI and RA4 exhibited a







FIGURE 10. MICROGRAPHS OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATES DA3 AND DA2 SHOWING: (a) 1100 A1 INTER-LEAF IN LAMINATE DA3; (b) 1100 A1 INTERLEAF IN LAMINATE DA2.







FIGURE 11. MICROGRAPHS OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE DAI SHOWING: (a) 1100 A1 INTERLEAF; (b) 7475 A1/1100 A1 INTERFACE.



(a)





FIGURE 12. MICROGRAPHS OF ROLL BONDED 7475 A1/1100 A1 LAMINATE RA4 SHOWING: (a) 1100 A1 INTERLEAF; (b) 1100 A1 INTERLEAF.



(a)





FIGURE 13. MICROGRAPHS OF ROLL BONDED 7475 A1/1100 A1 LAMINATE RA4 SHOWING: (a) DEBONDED AREAS AT 7475 A1/1100 A1 INTERFACES CAUSED DURING HEAT TREATMENT (TOP 7475 A1 LAYER IS AN OUTSIDE PANEL LAYER); (b) 7475 A1/1100 A1 INTERFACE.







FIGURE 14. MICROGRAPHS OF ROLL BONDED 7075 A1/7072 A1 LAMINATE RA1 SHOWING: (a) 7072 A1 INTERLEAF; (b) 7075 A1/7072 AT INTERFACE.



(a)



FIGURE 15. MICROGRAPHS OF EXPLOSIVE BONDED 7075 A1/7072 A1 LAMINATE EA1 SHOWING: (a) 7072 A1 INTERLEAF; (b) 7075 A1/7072 A1 INTERFACE.




FIGURE 16. MICROGRAPH OF DIFFUSION BONDED TI-6A1-4V/6061 A1 LAMINATE DTI SHOWING 6061 A1 INTERLEAF.

significant tendency for "cohesive" failure within the soft 1100 Al or 7072 Al interleaf, as will be discussed at more length in Section 3.3.

Explosive Bonded 7075 Al/7072 Al Laminate EAl Microstructure.

The microstructure of the explosive bonded laminate EAl was characterized by a remarkably smooth, well bonded interface between the 7075 Al primary alloy and the 7072 Al interleaf alloy, shown in Figure 15. The 7075 Al/7072 interface showed no evidence of waviness that would be characteristic of an over-welded explosively bonded system.

Diffusion Bonded Ti-6A1-4V/6061 Al Laminate DTI Microstructure.

Laminate DTI's microstructure is shown in Figure 16. Close examination of the Ti-6A1-4V/6061 Al interface using optical metallography and electron probe microanalysis revealed no evidence of chemical reaction at the interface.

Electron Probe Microanalysis of Laminate Panels. Electron probe microanalysis was used to evaluate the amount of chemical diffusion across the secondary metal interleaf alloys for all seven laminate configurations studied in this program. Diffusion profiles for the major alloying elements in the primary alloy across the secondary alloy interleafs are shown in Figures 17 through 21 for laminates DA1, RA4, RA1, EA1, and DT1. The diffusion gradients of Zn, Mg, and Cu were determined for the diffusion bonded, roll bonded, and explosive bonded Al/Al laminates, since these are the three principal alloying elements in both 7475 Al and 7072 Al. Figures i7 (DAI), 18 (RA4), 19 (RAI), and 20 (EAI) all illustrate diffusion gradients that show substantial diffusion of Zn, Mg and Cu from the primary alloy (7475 Al or 7075 Al) into the interleaf alloy (1100 Al or 7072 Al). This observation was noted for all the Al/Al laminates, regardless of whether the fabrication process was diffusion bonding, roll bonding, or explosive bonding. It was found, however, that the interleaf thickness significantly affected the diffusion profiles. This is shown in Figure 22 for the diffusion of Zn from the primary 7475 Al into 1100 Al in diffusion bonded laminates DA3, DA1, and DA2. These laminates had 1100 A1 interleaf thicknesses of 0.05 mm (0.002 in.), 0.13 mm (0.005 in.), and 0.25 mm (0.010 in.), respectively. As is evident from Figure 22 it is possible that sufficient diffusion had occurred in laminate DA3 (0.05 mm interleaf thickness) to make the interleaf hardenable by precipitation hardening thermal treatments. An increase in strength in the interleaf alloy could cause the laminate to fail




FIGURE 17. Zn, Mg, AND CU DIFFUSION PROFILES ACROSS 0.13 mm (0.005 ln.) 1100 A1 INTERLEAF IN DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE DA1 (HEAT TREATED TO -T7651 TEMPER).




FIGURE 18. Zn, Mg, AND Cu DIFFUSION PROFILES ACROSS 0.13 mm (0.005 IN.) 1100 AT INTERLEAS IN ROLL BONDED 7475 AT/1100 AT LAMINATE RA4 (HEAT TREATED TO -T7851 TEMPER).




FIGURE 19. Zn, Mg, AND Cu DIFFUSION PROFILES ACROSS 0.13 mm (0.005 in.) 7072 Al INTERLEAF IN ROLL BONDED 7075 Al/7072 Al LAMINATE RA) (HEAT TREATED TO -17651 TEMPER).




FIGURE 20. Zn, Mg, AND Cu DIFFUSION PROFILES ACROSS 0.13 mm (0.005 in.) 7072 A1 INTERLEAF IN EXPLOSIVE BONDED 7075 A1/7072 A1 LAMINATE EA1 (HEAT TREATED TO HAVE -T7651 TENSILE PROPERTIES).




FIGURE 21. A1 AND TI DIFFUSION PROFILES ACROSS 0.10 mm (0.004 in.) 6061 A1 INTERLEAF IN DIFFUSION BONDED TI-6A1-4V/6061 A1 LAMINATE DTI, HEAT TREATMENT (CONDITION A): AS RECEIVED [MILL ANNEALED + 1 HR AT 524°C (975°F)].




FIGURE 22. COMPARISON OF Zn DIFFUSION PROFILES ACROSS 1100 A1 INTERLEAVES OF DIFFERENT THICKNESSES IN 7475 A1/1100 A1 DIFFUSION BONDED LAMINATES DA1, DA2, AND DA3 (HEAT TREATED TO -T7651 TEMPER).

as a monolithic material rather than as separate layers as is required to achieve higher crack divider fracture toughness. Thus, the 0.05 mm interleaf was deemed too thin for use in diffusion bonded Al/Al laminates that must be subjected to precipitation hardening.

In comparing the diffusion gradients of laminates processed by the three different techniques, it was found that the diffusion profiles across the secondary alloy interleaves were very similar. Direct comparisons alloy-to-alloy for a given interleaf thickness (0.13 mm) for diffusion bonding vs. roll bonding and roll bonding vs. explosive bonding are shown in Figures 23 and 24. It was anticipated that the diffusion bonding and roll bonding fabrication techniques would yield microstructures having similar diffusion gradients; however, the similar behavior of explosive bonded laminate EAI is somewhat unexpected, since this laminate was heated to only 160°C (320°F) during aging to achieve -T76 tensile properties. The microanalysis results shown in Figures 20 and 24 clearly show that extensive diffusion of Zn, Mg, and Cu occurred in laminate EAI due to the 160°C (320°F) aging treatment.

3.3 FRACTURE PROPERTIES OF LAMINATE PANELS

3.3.1 Fracture of Crack Divider Metal/Metal Laminates

Practure Results. The fracture toughness values of diffusion bonded 7475 A1/1100 A1 laminates DA1, DA2, and DA3 are given in Table 13. Fracture results on roll bonded 7475 A1/1100 A1 laminate RA4 are given in Table 14. These fracture results were all determined on laminate material heat treated to the -T7651 primary alloy temper. All tests were conducted with the single-edge-notched specimen configuration (Figure 5), with the exception only of additional compact tension tests for laminates DA1 and RA4. These tests were included to evaluate specimen geometry effects, since the compact tension specimen was selected for use in fatigue crack propagation testing described in Section 3.4.1. It is evident from comparing SEN and CT fracture results for DA1 and RA4, no significant differences in fracture properties were noted for tests completed with these two specimen types.

The results illustrated in Tables 13 and 14 show that all laminate panels had remarkably improved critical fracture toughness (K_C)




FIGURE 23. COMPARISON OF Zn DIFFUSION PROFILES ACROSS 1100 A1 INTER-LEAVES FOR 7475 A1/1100 A1 ROLL BONDED AND DIFFUSION BOND-ED LAMINATES RA4 AND DA1.




FIGURE 24. COMPARISON OF Zn DIFFUSION PROFILES ACROSS 7072 AT INTERLEAVES FOR 7075 AT 7072 AT ROLL BONDED AND EXPLOSIVE BONDED LAMINATES RAT and EAT.

TABLE 13. CRACK DIVIDER, L-T ORIENTATION FRACTURE TOUGHNESS VALUES OF DIFFUSION BONDED 7475 AI/i100 AI LAMINATE PANELS

			_			-			
CRITICAL FRACTURE TOUGHNESS, K	MPa√m (ksi√in)	97.8 (89.0) 105.7 (96.2) 106.4 (96.9)	1	98.8 (89.9) 100.1 (91.1) 100.8 (91.7)	- 1	1	92.9 (84.5) 101.4 (92.3) 103.7 (94.4)	avg. 99.3 (90.4)	103.5 (94.2)
APPARENT FRACTURE TOUGHNESS, RAPP	MPa√m (ksi√in)	64.4 (58.6) 67.1 (61.1) 69.2 (63.0)	1	71.7 (65.2) 73.9 (67.2) 73.2 (66.6)	- 1	1	63.3 (57.6) 65.6 (59.7) 66.4 (60.4)	avg. 65.1 (59.2)	69.6 (63.3)
CONDITIONAL FRACTURE TOUGHNESS, KQ	MPa√m (ksi√in)	41.3 (37.6) 37.5 (34.1) 39.2 (35.7)	avg. 55.5 (55.0)	41.3 (37.6)	39.6	1	41.5 (37.8) 38.8 (35.3) 38.0 (34.6)		40.1 (36.5)
MAX IMUM LOAD	kN (kips)	71.2 (16.0) 55.2 (12.4) 56.9 (12.8)		18.7 (4.20)			48.9 (11.0)		53.8 (12.1)
5% OFFSET LOAD	kN (kips)	45.8 (10.3) 30.8 (6.93) 32.3 (7.27)		10.8 (2.42)			30.6 (6.89) 29.0 (6.52) 27.7 (6.23)		1.1 (7.00)
CRITICAL CRACK LENGTH	(in.)	(0.608) (0.823) (0.814)		(1.204)	(1.208)		(0.822) (0.832) (0.862)		(0.666) 20.5 (0.808) 31.1 (7.00) 53.8 (12.1)
INITIAL CRACK LENGTH	(in.) mm	(0.466) 15.4 (0.662) 20.9 (0.661) 20.7	-		(1.018) 30.7		(0.686) 20.9 (0.679) 21.1		
SPECIMEN	mm	11.8 16.8 16.8		25.9 CT 25.9			17.4 SEN 17.2		SEN 16.9
SECONDARY ALLOV (1100 A1) THICKNESS	(in.)		4 (50.005) L	500.0			0.25 (0.010)		0.05 (0.002)
LAMINATE SI PANEL DESIGNATION							DAZ		, DA3

 $^\circ$ Laminates were heat treated to give -7765; properties to the primary metal phase (7475 A1). *** Laminate panels were nominally 11.9 mm (0.47 in.) thick.

*** Primary alloy (7475 A1) layers were nominally 2.3 mm (0.090 in.) thick.

works SEN - single-edge-notched fracture specimen, CT - compact tension fracture specimen.

alonii kanteessa kasta masta masta sa sa kasta sa kasta sa kasta sa ka ta mana masta sa ka ka ka ka ka ka ka k

TABLE 14. CRACK DIVIDER, L-T ORIENTATION FRACTURE TOUGHNESS VALUES OF ROLL BONDED 7475 A1/1100 A1 AND 7075 A1/7072 A1 LAMINATE PANELS

The second secon

	_						
CAL GRE NESS	HPavm (ksivin.)	(80.4) (80.2) (50.1)	(80.2)	(81.8) (80.7) (91.1)	(84.5)	(51.4) (52.3)	(54.0)
CRITICAL FRACTURE TOUGHNESS	MPavm (I	98.4 4.88 5.88 5.88	1 1	89.9 88.7 100.i	avg. 92.9	56.5 57.5	
			avg.	 	avg		, 5 8
APPARENT FRACTURE TOUGHNESS	MPavm (ksivin.)	(57.8) (59.1) (59.1)	(58.7)	(65.8) (65.1) (69.5)	(8.8)	(41.1)	(42.5)
APPARENT FRACTURE TOUGHNES	MPavm	29.27 12.02.0		72.3 71.5 76.4	avg. 73.4	45.2 46.5	
	_		avg.		avg		avg.
CONDITIONAL FRACTURE WOUGHNESS	MPavm (ksivin.)	(39.1) (40.3)	(40.1)	(43.6) (43.6) (43.6) (46.7)	(44.6)	(30.7)	(30.2)
COND (T. I.O.R. FRACTURE TOUGHNES	MPa√m	£4.0 £4.0	3vg. 44.0	47.9 47.9 51.3	avg. 49.0	33.7	33.2 avg. 33.6
		1332		566		<u> </u>	
MAX I HUH LOAD	(k1ps)	(10.5)		(4.06) (4.10) (3.90)		(7.28)	
Ă,	K	14.2		18.1		32.4	35.3
5% OFFSET LOAD	(kips)	(6.78)	(05.0)	(2.69) (2.74) (2.62)		(5.44)	(5.44)
07 85	KK	31.6 30.2	. Š	12.0		24.2	24.2
CRITICAL CRACK LENGTH	(in.)	(0.822) (0.840)	(0.65/)	(1.189)	•	(0.796)	(0.810)
CR1 CR4 LEN	Æ	20.9	5.1.3	36.2 29.9		20.2	20.6
INITIAL CRACK LENGTH	(in.)	(0.706)	(0.732)	(1.065)		(0.718)	(0.712)
	mu	17.9	9. 9.	27.1	?	18.2	18.1
SPECIMEN		SEN		15		į	2
PRIMARY/ SECONDARY ALLOYS			7475 A1/			7075 A1/	/0/2 A!
LAMINATE PANEL DESIGNATION			100			8.4	

? Laminates were heat treated to give -T7651 properties to the primary metal phase.

 $^{\circ\circ}$ Laminate panels were nominally 11.9 mm (0.47 in.) thick.

and Primary alloy layers were nominally 2.3 mm (0.090 in.) thick, while secondary alloy layers were nominally 0.13 mm (0.005 in.) thick.

esem SEN - single-edge-notched fracture specimen; CT - compact tension fracture specimen.

values above the corresponding monolithic 7475-T7651 values listed earlier in Table 7 of Section 3.1. (Critical fracture toughness is considered the most representative measure of toughness improvement in these laminate materials, since they do not approach plane strain fracture behavior. This same conclusion has been reached by previous investigators 3 , 7 , who used 6 C as the most representative measure of toughness in crack divider laminates). Table 15 shows comparative average 6 C values for single layer 7475 -T761 A1, monolithic 7475 -T7651 A1 plate, and diffusion bonded and roll bonded 7475 A1/1100 A1 laminates. Several observations can be made from the comparisons given in Table 15:

- (1) The diffusion bonded 7475 Al/1100 Al laminates DAI, DA2 and DA3 had essentially the same fracture toughness, regardless of the secondary alloy interleaf thickness.
- (2) The diffusion bonded laminates possessed significantly higher $K_{\rm C}$ values than monolithic 7475 Al of the same thickness. This improvement in $K_{\rm C}$ ranged from 50% to 56%.
- (3) The single layer 7475 Al sheet toughness was retained in all diffusion bonded laminates. The $K_{\rm C}$ values of these laminates were even slightly higher than the average $K_{\rm C}$ value for the single layer sheet from which these laminates were composed.
- (4) The roll bonded 7475 Al/1100 Al laminate RA4 showed a significantly higher (33%) average $K_{\rm C}$ value over monolithic 7475 Al of the same thickness.
- (5) The single layer 7475 Al sheet toughness was retained in roll bonded laminate RA4. The average $K_{\rm C}$ value of the laminate was essentially the same as the average $K_{\rm C}$ value for 7475 Al single layer sheet of the same thickness as the primary 7475 layers in the laminate.

Roll Bonded and Explosive 7075 Al/7072 Al Laminate Fracture Results. The fracture toughness values for roll bonded and diffusion bonded 7075 Al/7072 Al laminates RAI and EAI are given in Table 14 and 16. These fracture results were determined on laminate material heat treated to have -T76 tensile properties. All tests were conducted using the SEN specimen. As was

COMPARISON OF AVERAGE CRITICAL FRACTURE TOUGHNESS VALUES (CRACK DIVIDER, L-T ORIENTATION) FOR 7475-T761 A1 SHEET, MONOLITHIC 7475-T7651 A1 PLATE, AND D:FFUSION BONDED AND ROLL BONDED 7475 A1/1100 A1 LAMINATE PANELS TABLE 15.

_ 				 	
% INCREASE ABOVE MONOLITHIC	PLATE TOUGHNESS			56 % 568 50%	%E
8 RETENTION OF SINGLE				1158	836
	(ksi√in)	(82.0)	(60.3)	(94.2) (94.0) (90.4)	(80.2)
CRITICAL FRACTURE	MPavm	90.1	66.3	103.5 103.3 99.3	88.2
1100 AT INTERLET THICKNESS	mm (in.)	,	!	0.05 (0.002) 0.13 (0.005) 0.25 (0.010)	0.13 (0.005)
NOM I NAL THI CKNËSS	mmr. (in.)	2.3 (0.090)	11.9 (0.47)	0) (24.0) 6.11	11.9 (0.47)
MATERIAL	E .	Single Layer 7475-T761 Al Sheet	Monolitaic 7475-17651 Al Plate	Diffusion Bonded 7475 A1/1100 A1 Laminates	Roll Bonded 7475 Al/1100 Al 11

 $^{*}\mathrm{K}_{\mathsf{C}}$ values determined using single-edge-notched fracture specimens.

**Laminate panels heat treated to -T7651 temper.

TABLE 16. CRACK DIVIDER, L-T ORIENTATION FRACTURE TOUGHNESS VALHES OF EXPLOSIVE BOPDED 7075 A1/7072 A1 LAMINATE EA! AGED AT 163°F (325°F) FOR 2.8 HOURS

, .	CRITICAL FRACTURE TOUGHNESS	" Parm (ksirin)	64.3 (58.5) 69.9 (63.6) 63.3 (57.6) avg.65.8 (59.9)	
	APFARENT FRACTURE TOUGHNESS	HPavm (ksivin)	8.0 (43.7) 50.0 (45.5) 46.4 (42.2) avg. 48.1 (43.8)	
•	CONDITIONAL FRACTURE TOULANESS	MPa/m (ksi/in)	35.9 (32.7) 35.1 (31.9) 35.1 (51.9) avg. 35.4 (32.2)	
١.	MAX (NUM LOAD	KN (kips)	37.1 (8.34) 38.8 (8.72) 35.5 (7.98)	
	5% OFFSET LOAD	kn (kips)	27.7 (5.22) 37.1 27.2 (6.12) 38.8 26.8 (6.03) 35.5	
	CRITICAL CRACK LENGTH	me (in.,	20.5 (0.807) 20.9 (0.821) 20.8 (0.820)	
	INITIAL CRACK LENGTH	mm (in.)	17.9 (0.705) 17.9 (0.704) 18.i (0.712)	
	SPECIMEN		SEN	
	PRIMARY/ SECONDARY ALLOYS		7075 A1/ 7072 A1	
	LAMINATE PANEL DESIGNATION		EA .	

Laminate pane, 521 was nominally 12 to mm (o ho to) shint

** SFN - single-edge-notched fracture specimen.

the case for the diffusion bonded and roll bonded 7475 Al/1100 Al laminates, the roll bonded and explosive bonded 7075 Al/7072 Al laminates possessed significantly higher $K_{\rm C}$ values than corresponding monolithic 7075-T7651 Al of the same thickness. Also, the single layer 7075 Al sheet toughness was completely retained in the 7075 Al/7072 Al laminates. Comparative $K_{\rm C}$ values for single layer 7075-176 Al sheet, monolithic 7075-T7651 Al plate, and roll bonded and explosive bonded 7075 Al/7072 Al laminates RA1 and EAl are given in Table 17. Observations similar to those made earlier for the 7475 Al/1100 Al laminates can be made for the 7075 Al/7072 Al laminates based on Table 17:

- (1) The roll bonded 7075 Al/7072 Al laminate RAl showed a significant improvement in K_c over monolithic 7075 Al of the same thickness.
- (2) The single layer 7075 Al sheet toughness was retained in the roll bonded laminate. The average $K_{\rm c}$ value of the laminate was only 7% lower than the average $K_{\rm c}$ value for 7075 Al single layer sheet of approximately the same thickness as the primary 7075 layers in the laminate.
- (3) The explosive bonded laminate EA1 possessed a K_c value that was 50% higher than monolithic 7075 A1 of the same thickness.
- (4) The single layer 7075 Al sheet toughness was retained in the explosive bonded laminate. The laminate had an average $K_{\rm C}$ value that was 3% higher than that for single layer 7075 Al sheet of approximately the same thickness as the primary 7075 Al layers in the laminate.

Diffusion Bonded Ti-5A1-4V/6061 Al Laminate DTI Fracture Results.

The fracture toughness values of diffusion bonded Ti-6A1-4V/6061 Al laminate DTI are given in Table 18. The fracture results were determined on laminate specimens heat treated to the two states discussed in Section 3.1 and 3.2: Condition A (as-received) and Condition B (to give higher strength to the 6061 Al interleaf). All tests were conducted using the single-edge-notched fracture specimen. Although there was a slight difference in fracture values between Condition A and Condition B heat treat states, this difference did not seem to be of significance, especially when compared to the Condition A

CUMPARISON OF AVERAGE CRITICAL FRACTURE TOUGHNESS VALUES (CRACK DIVADER, L-T ORIENTATION) FOR 7075-176 AL SHEET, GONOLITHIC 7075-17651 AL PLATE, AND ROLL BOHDED AND EXPLOSIVE BONDED 7075 AL/7072 ALLAMINATE PANELS TABLE 17.

MATERIAL	NOM!%AL THICKNESS mm (in.)	7072 A1 INTERLEAF THICKNESS mm (in.)	CRITICAL FRACTURE TOUGHNESS, K _c MPavm (ksivin)	% RETENTION OF SINGLE LAYER SHEET TOUGHNESS	E INCREASE ABOVE MONOLITHIC PLATE TOUGHNESS
Single Layer 7075-T76 Al Sheet	2.3 (0.09¢)		63.7 (57.9)		
Monolithic 7075-17651 Al Plate	12.7 (0.50)		44.0 (40.0)		!
Rolled Bonded 7075 Al/7072 Al Laminate	(74.0) 6.11	0.13 (0.005)	59.4 (54.0)	93%	35%
Explosive Bonded 7075 A1/7072 A1 Laminate	12.4 (0.49)	0.13 (0.005)	(6-65) 8:59	1033	50%

 $^{^{\}star}$ K values determined using single-edge-notched fracture specimens.

^{**} Laminate panels heat treated to -17651 and -176 tempers for roll bonded and explosive bonded panels, respectively.

TABLE 18. CRACK DIVIDER, L-T ORIENTATION FRACTURE TOUGHNESS VALUES OF DIFFUSION BONDED TI-6AI-4V/6061 A! LAMINATE DTI

			
FRACTURE ESS, K (½sí√in.)	(113) (133) (127) (124)	(135) (136) (128) (133)	
CRITICAL FRACTURE TOUGHNESS, K _C NPa:/m (ksi/i	124 146 140 avg. 137	148 149 141 avg. 146	
FRACTURE S, Kapp (ksivin.)	(82.7) (87.7) (78.6) (83.0)	(83.8) (102) (53.9) (89.9)	
APPARENT FRACTURE TOUGHNESS, K APP	90.9 95.4 86.4 avg. 91.2	92.1 112 92.2 avg. 98.2	
TIONAL FRACTURE TOUGHNESS, K _Q Pa/m (ksi/in.)	(67.8) (57.2) (51.4) (58.8)	(49.2) (56.9) (50.7) (52.3)	
CONDITIONAL FRACTURE TOUGHNESS, K _Q	74.5 62.9 56.5 avg. 64.6	54.1 62.5 55.7 avg. 57.4	
MAXIMUM LOAD (kips)	(10.7) (15.6) (14.8)	(18.9) (16.3) (13.3)	
N N	47.6 69.4 65.8	84.1 72.5 59.2	
5% OFFSET LOAD N (kips)	(8.74) (10.2) (9.64)	(11.1) (9.08) (8.04)	
₹ \$\frac{1}{2}	38.9 45.4 42.9	4.9.4 4.0.4 35.8	
CRITICAL CRACK LENGTH	(0.965) (0.895) (0.897)	(0.841) (0.893) (0.934)	
CRITIC	24.5 22.7 22.8	21.4 22.7 23.7	
INITIAL CRACK LENGTH	(0.864), 24.5 (0.754) 22.7 (0.755) 22.8	(0.674) 21.4 (0.797) 22.7 (0.795) 23.7	
N. E	21.9 19.2 18.7	17.1 20.2 20.2	
HEAT	Condition A	Condition B	

* Laminate panel DT1 was nominally 13.2 mm (0.52 in.) thick.

** Fracture values determined using single-edge-notched specimens.

*** Primary alloy (Ti-6Al-4V) layers were nominally 3.2 mm (0.125 in.) thick, while secondary alloy (6061 Al) layers were nominally 0.10 mm (0.00½ in.) thick.

***** Condition A: as received plate [mill annealed + 1 hr $\in 524^{\circ}\text{C}$ (975°F)].

***** Condition B: as received plate [mill annealed + 1 hr £ 524°C (975°F)] + 1 hr \$ 527°C (980°F), water quench, 18 hr @ 160°C (320°F).

and B tensile and fracture values of single layer 3.2 mm (0.125 in.) Ti-6A1-4V sheet in Tables 6 and 8. Both Condition A and B heat treat states showed much higher critical fracture toughness compared to monolithic Ti-6A1-4V plate of the same thickness. Table 19 summarizes the comparative critical fracture toughness values for single layer Ti-6A1-4V sheet, monolithic Ti-6A1-4V plate, and diffusion bonded Ti-6A1-4V/6061 Al laminate DTI (all in the Condition A state). The following observations can be made from these results:

- (1) The diffusion bonded Ti-6Al-4V/6061 Al laminate possessed an average critical fracture toughness that was 117% higher than corresponding monolithic Ti-6Al-4V plate of the same thickness.
- (2) The single layer Ti-6Al-4V sheet toughness was essentially retained in the Ti-6Al-4V/606l Al laminate. The average $K_{\rm C}$ value for the laminate was 12% less than that for single layer Ti-6Al-4V sheet of the same thickness as the primary titanium layers in the laminate.

Failure in Laminate Panels. It was found that all laminate fracture specimens tested under this program exhibited plane stress (or slant) failure surfaces of the individual primary layers. Failure surfaces of several SEN fracture specimens are shown in Figures 25 and 26. The plane stress failure behavior of the individual layers contrasted sharply with the predominantly plane strain (or flat) failure surfaces exhibited by the monolithic baseline 7475 Al, 7075 Al, and Ti-6Al-4V plate specimens (two of which are shown in Figure 26). The plane stress failure of the individual primary layers is indicative of the much higher toughness values noted for these laminates. Similar failure surfaces in laminated panels have been noted in previous evaluations of laminate failures by other workers and this type of failure mechanism is considered essential for obtaining high toughness in laminate materials.

開発を選

Fractography of fracture specimens from each of the seven laminate systems was conducted using scanning electron fractography. Fractographs illustrating the various modes of failure in these laminates are given in Figures 27 through 32. It was found that all diffusion bonded laminates (both 7475 Al/1100 Al and Ti-6Al-4V/6061 Al) exhibited "adhesive" delamination at the primary/secondary alloy interface. Fractographs illustrating this type of failure in these laminates are shown in Figures 27 and 28. It was noted


COMPARISON OF AVERAGE CRITICAL FRACTURE TOUGHNESS VALUES (CRACK DIVIDER, L-T ORIENTATION) FOR TI-6A1-4V SHEET AND MONOLITHIC PLATE AND DIFFUSION BONDED TI-6A1-4V/6061 A1 LAMINATE PANEL DTI. TABLE 19.

是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们

MATERIAL	NOMINAL THICKNESS mm (in.)	6061 A1 INTERLEAF THICKNESS mm (in.)	CRITICAL FRACTURE TOUGHNESS, K MPa/m (ksi/in		% RETENTION OF SINGLE LAYER SHEET TOUGHNESS	% INCREASE ABOVE MONOLITHIC PLATE TOUGHNESS
Single Layer Ti-6Al-4V Sheet	3.2 (0.125)	÷	1) 551	(141)	-	
Monolithic Ti-6A1-4V Plate	13.7 (6.54)		62.8 (5	(57.1)	-	
Diffusion Bonded Ti-6Al-4v/6061 Al Laminate	13.2 (0.52)	0.10 (0.004)	1) 281	(124)	88%	1178

*All materials in Condition A heat treat condition: mill annealed + 1 hr @ 524°C (975°F).

 $^{**}\mathsf{K}_\mathsf{C}$ values determined using single-edge-notched fracture specimens.







FIGURE 25. FAILURE SURFACES OF CRACK DIVIDER SEN SPECIMENS, IDENTIFIED LEFT TO RIGHT: (a) DIFFUSION BONDED 7475 A1/1100 A1 LAMINATES DA3, DA1, DA2; (b) ROLL BONDED 7075 A1/7072 A1 LAMINATE RA1, ROLL BONDED AND DIFFUSION BONDED 7475 A1/1100 A1 LAMINATES RA4 AND DA1.






FIGURE 26. FAILURE SURFACES OF CRACK DIVIDER SEN FRACTURE SPECIMENS, IDENTIFIED LEFT TO RIGHT: (a) DIFFUSION BONDED Ti-6A1-4V/6061 LAMINATE DT1, MONO-LITHIC Ti-6A1-4V; (b) ROLL BONDED AND EXPLOSIVE BONDED 7075 A1/7072 A1 LAMINATES RA1 AND EA1, MONOLITHIC 7075 A1.






FIGURE 27. FRACTOGRAPHS OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE DA1 SEN FAILURE SURFACE: (a) "ADHESIVE" DELAMINATION AT 1100 A1 INTERLEAF; (b) 1100 A1 "ADHESIVELY-FAILED SURFACE".





FIGURE 28. FRACTOGRAPH OF DIFFUSION BONDED 7475 A1/1100 A1 LAMINATE DA3 SEN FAILURE SURFACE SHOWING "ADHESIVE" DELAMINATION OF 1100 A1 INTERLEAF FROM ADJACENT 7475 A1 PRIMARY LAYERS.







FIGURE 29. FRACTOGRAPHS OF ROLL BONDED LAMINATES RAI AND RA4 SEN FAILURE SURFACES: (a) "COHESIVE" FAILURE IN 7072 AI INTERLEAF IN RAI; (b) "ADHESIVE" DELAMINATION AT 7475 AI/1100 AI INTERFACE IN RA4.



FIGURE 30. FRACTOGRAPH OF ROLL BONDED 7075 A1/7072 A1 LAMINATE RA1 SEN FAILURE SURFACE SHOWING SHEAR LIP SURFACES OF 7075 A1 PRIMARY LAYERS AND DIMPLED RUPTURE FAILURE IN 7072 A1 INTERLEAVES (A) AND (B) AND "ADHESIVE" DELAMINATION AT (C).






FIGURE 31. FRACTOGRAPHS OF 7075 A1/7072 A! ROLL BONDED (RAI) AND EXPLOSIVE BONDED (EAI) LAMINATES SEN FAILURE SURFACES SHOWING DIMPLED RUPTURE ACROSS 7072 A1 INTERLEAVES:
(a) RAI; (b) EAI.





FIGURE 32. FRACTOGRAPH OF DIFFUSION BONDED TI-6A1-44/6061 AT LAMINATE DTI SEN FAILURE SURFACE SHOWING DEVELOP-MENT OF SHEAR LIPS IN ADJACENT TI-6A1-4V LAYERS.

previously that all diffusion bonded 7475 Al/1100 Al failed at essentially the same toughness level, regardless of interleaf thickness. The "adhesive" nature of bondline failure in these laminates precluded any evaluation of interleaf thickness effects on the fracture toughness, since the interleaf strength level had no effect on the bondline separation (delamination) strength...


In the roll bonded 7475 Al/1100 Al and 7075 Al/7072 Al laminates it was found that both "adhesive" delamination and "cohesive" interleaf failure occurred, as illustrated in Figures 29, 30 and 31. The mixed "adhesive", "cohesive" failure modes in the roll bonded laminates had no effect on development of plane stress failure shear lips in the primary layers in these laminates. The "cohesive" failure mode in the interleaf is preferable to "adhesive" failure, since the failure strength of the bonuline can be easily controlled and predicted. If the failure is "adhesive" in nature, little control can be exercised over what strength the bondline will fail, and premature or excessive delamination could result. The explosive bonded 7075 Al/7072 Al laminate exhibited 100% dimpled rupture across the 7072 Al interleaf and had very little tendency to separate completely in the bondline, as shown in Figure 31. The low strength and high ductility of the 7072 Al interleaf material in this laminate allowed full development of plane stress shear lips in all primary 7075 Al layers. It was considered that this laminate failed in an "ideal" manner.

A schematic illustration of the failure modes discussed in the previous paragraphs is shown in Figure 33. This figure shows the well known transition from flat fracture (plane strain) for thick sections to slant fracture (plane stress) for thin sections. The baneficial effect for obtaining plane stress failure in thick laminated panels was documented in Tables 15, 17 and 19 earlier. Figures 34 and 35 show experimental load/crack-opening displacement record comparisons for laminated and monolithic 7475 Al (Figure 34) and laminated and monolithic Ti-6Al-4V (Figure 35). These show dramatically the effect that plane stress failure in laminated panels has on the ultimate load carrying capacity of a thick section. The improvement in fracture toughness that can be achieved through lamination is summarized schematically in Figure 36. Here it is shown that:


(1) The toughness of a laminate depends ultimately on the plane stress toughness of the individual layers comprising the laminate.



TRANSITION IN FAILURE APPEARANCE FROM FLAT FRACTURE FOR THICK SECTIONS UNDER PLANE STRESS FIGURE 33.



COMPARISON OF LOAD/CRACK-OPENING-DISPLACEMENT FRACTURE TOUGHNESS TEST RESULTOR DIFFUSION BONDED 7475 AI/1100 AI LAMINATE DAI AND MONOLITHIC 7475-T7653. PLATE, CRACK DIVIDER, L-T ORIENTATIONS. FIGURE 34.



COMPARISON OF LOAD/CRACK-OPENING-DISPLACEMENT FRACTURE TOUGHNESS TEST RESULTS FOR DIFFUSION BONDED TI-6A1-4V/6O61 A1 LAMINATE DTI AND MONOLITHIC TI-6A1-4V PLATE, CRACK DIVIDER, L-T ORIENTATIONS. FIGURE 35.




FIGURE 36. EFFECT OF LAMINATION ON CRACK DIVIDER FRACTURE TOUGHNESS

(2) Maximum toughness is achieved by selecting the primary layer thickness to correspond to that thickness at which the K_C vs. thickness curve for single layer metal reaches a peak.

These conclusions are based on the important requirement that the primary layers in a laminate be bonded together in such a way that they fail individually under plane stress conditions. This fact has been recognized by numerous investigators of laminate fracture properties. The key factor controlling plane stress failure of the primary layers is that failure occur in the interleaf bondline prior to development of a plane strain condition through the thickness of the laminate. This means that the interleaf bondline strength must be somewhat lower than the primary metal strength. A higher ductility in the interleaf metal insures that excessive delamination does not occur.

3.3.2 Fracture of Crack Arrest Metal/Metal Laminates

The crack arresting properties of metal/metal laminates are as attractive as the fracture toughness properties of crack divider laminates, if not more so. Three point bend fracture specimens of L-S, crack arrest orientation (Figure 6) were used to document the crack arrest properties of the seven laminate configurations evaluated in this investigation. Corresponding tests were also conducted on monolithic 7475 Al, 7075 Al, and Ti-6Al-4V piate. The crack arrest properties for all laminate materials tested under rising load are given in Table 20. As noted in Table 20, with only one exception, every laminate specimen tested under rising load fracture conditions arrested the propagating crack at the first interleaf the crack encountered. Typically these three point bend specimens had notches of 1.3 mm (0.050 in.) depth with fatigue precracks of 0.25 mm (0.010 in.) length. The specimens were tested under rising load and the following sequence was noted for each specimen:

- (1) The load increased until the primary layer containing the crack suffered catastrophic failure.
- (2) The crack did not propagate beyond the first secondary alloy interleaf that it encountered.
- (3) Loading was continued until the specimen was subjected to a total mid-span stroke displacement of 10.2 mm (0.4 in.).

CRACK ARREST, L-S ORIENTATION THREE POINT BEND FRACTURE TEST RESULTS FOR ALL LAMINATED PANELS **TABI.E** 20.

このようななな ははないない のはまないという

REMARKS	Also, delamination @ 3rd interleaf	Crack arrested @ 2nd interleaf		·			Also, delamination @ 2nd interleaf
CRACK ARREST @ 1st INTERLEAF	Yes Yes Yes	Yes No Yes	Yes	Yes Yes Yes	Yes Yes Yes	Yes Yes Yes	Yes Yes Yes
TEST NO.	- 2 K	1 3 3	Į.	1 2 3	1 2 3	1 2 3	1 2 3
BOND I NG PROCESS	Diffusion	Diffusion	Diffusion	Roll	Roll	Explosive	Diffusion
PRIMARY/ SECONDARY ALLOYS	7475 A1/ 1100 A1	7475 A1/ 1100 A1	7475 A1/ 1100 A1	7075 A1/ 7072 A1	7475 A1/ 1100 A1	7075 A1/ 7072 A1	Ti-6Al-4V/ 6061 Al
LAMINATE PANEL DESIGNATION	DA1	DA2	DA3	RAI	RA4	EA1	DT1 (Condition A)


In two of the specimens tested in this manner, secondary delamination occurred at high loads in interleaf bondlines other than the one which arrested the crack. In all other tests loading after crack arrest caused general yielding of the specimen, but no crack extension was noted.

This behavior contrasted sharply with the three point bend behavior of similarly fatigue precracked L-S orientation TPB specimens of monolithic plate metal. As would be expected, all monolithic plate alloys (7475 Al, 7075 Al, and Ti-6Al-4V) suffered catastrophic failure once the critical crack extension load had been attained. Figure 37 shows load/crack-opening-displacement failure records that demonstrate the sharp difference in behavior observed for diffusion bonded Ti-6Al-4V/6061 Al laminate DTI and monolithic Ti-6Al-4V plate specimens. Typical TPB failure specimens tested in the manner described are shown in Figures 38 and 39. The results discussed here show that these metal/metal laminate systems all possessed a substantial capacity for arresting cracks that had become catastrophic in nature under rising load condition. This same crack arrest potential documented for cracks propagating under rising loads was also established for cracks propagating under fatigue loads, as described later in Section 3.4.2.

3.4 FATIGUE CRACK PROPAGATION IN LAMINATE PANELS

3.4.1 Fatique Crack Propagation in Crack Divider Metal/Metal Laminates


Compact tension specimens (Figure 4) were used to document the crack divider, fatigue crack propagation rates in 7475-T761 Al sheet, Ti-6Al-4V sheet, monolithic 7475-T7651 Al plate, monolithic Ti-6Al-4V plate, roll bonded 7475 Al/1100 Al laminate RA4, and diffusion bonded Ti-6Al-4V/6061 Al laminate DTI. These tests were conducted at room temperature at 10 Hz and an R ratio (ratio of minimum to maximum load) of 0.1. The results for 11.9 mm (0.47 in.) roll bonded laminate RA4 are shown in Figure 40, while the results for 2.3 mm (0.090 in.) 7475 Al sheet and 11.9 mm (0.47 in.) monolithic 7475 Al are given in Figures 41 and 42. Figure 43 gives the relative comparisons between these three materials. Although there are some differences in the propagations rates at given stress intensity range values for these three material types, these differences are not large and are not attributable to any effects from lamination. These results are not unexpected since the



The second secon

COMPARISON OF LOAD/CRACK-OPENING-DISPLACEMENT THREE POINT BEND FRACTURE TEST TESULTS FOR DIFFUSION BONDED TI-6A1-4V/6061 AI LAMINATE DTI AND MONOLITHIC TI-6A!-4V PLATE, CRACK ARREST, L-S ORIENTATIONS. FIGURE 37.

and the second s





20 mm

FIGURE 38. THREE POINT BEND FRACTURE SPECIMENS FOR DIFFUSION BONDED 7475 A1/1100 A1 LAMINATES DA1, DA2, DA3:
(a) CPACK ARREST AT FIRST 1100 A1 INTERLEAF (DA3, DA1, DA2 TOP TO BOTTOM); (b) CRACK ARREST IN DA1 (TOP) AND DA2, BUT DELAMINATION IN THIRD 1100 A1 INTERLEAF IN DA1.



20 mm

(a)




FIGURE 39. THREE POINT BEND FRACTURE SPECIMENS: (a) EXPLOSIVE BONDED 7075 A1/7072 A1 LAMINATE EA1 SHOWING CRACK ARREST AT FIRST 7072 A1 INTERLEAF; (b) DIF-

The state of the s

(b)

FUSION BONDED TI-6A1-4V/6061 A1 LAMINATE DT1 (TOP) SHOWING CRACK ARREST AT FIRST 6061 A1 INTERLEAF; MONOLITHIC TI-6A1-4V PLATE SHOWING TOTAL FAILURE.




FIGURE 40. FATIGUE CRACK PROPAGATION RATES FOR 11.9 mm (0.47 in.) THICK ROLL BONDED LAMINATE RA4, CRACK DIVIDER, L-T ORIENTATION.




FIGURE 41. FATIGUE CRACK PROPAGATION RATES FOR 2.3 mm (0.090 in.) THICK 7475-T761 A1, L-T ORIENTATION.




FIGURE 42. FATIGUE CRACK PROPAGATION RATES FOR 11.9 mm (0.47 in.) THICK 7475-T7651 A1, L-T ORIENTATION.




FIGURE 43. COMPARISON OF FATIGUE CRAC" PROPAGATION RATES FOR MONCLITHIC 7475-T761, -T7651 A' SHEET AND PLATE AND ROLL BONDED LAMINATE RA4, CRACK DIVIDER, L-T ORIENTATION.

basic size of the plastic zone at the crack tip is significantly smaller under facigue loading than under rising loading. The development of large plastic zones under plane stress conditions is the key factor which allows crack divider laminates to possess significantly higher fracture toughness than corresponding monolithic metal. Except at high stress intensity factor ranges, the plastic zone size in fatigue is small regardless of specimens thickness; thus, there is relatively little section thickness effect on fatigue crack propagation rates.

The crack divider fatigue crack propagation test results for 3.2 mm (0.12 in.) Ti-6A1-4V sheet; 13.2 mm (0.52 in.) diffusion honded Ti-6A1-4V/6061 A1 laminate DTI, and 13.7 mm (0.54 in.) Ti-6A1-4V monotithic plate are given in Figures 44 through 47. Except at high stress intensity factor ranges (where the plastic zone size may be affected by the specimen thickness), essentially the same considered can be made regarding the Ti-6A1-4V materials as was noted above for the 7475 Al materials. At the high stress intensity factor ranges (ΔK) for the Ti-6A1-4V materials, the curves in Figure 47 separate farther with the thinnest material (3.2 mm thick sheet) having the lowest fatigue crack growth rate and the 13.7 mm monolithic plate material having the highest growth rate. The differences in growth rates at the high ΔK ranges could be attributable to decrease in the plastic zone size from thin section to thick section.

3.4.2 Fatigue Crack Propagation in Crack Arrest Metal/Metal Laminates

Three point bend, L-S crack arrest orientation fracture tests were confucted on 11.9 mm (0.47 in.) roll bonded 7475 Al/1100 Al laminate RA4, 11.3 mm (0.47 in.) monolithic 7475-T7651 Al plate, 13.2 mm (0.52 in.) diffusion bonded Ti-6Al-4V/6061 Al laminate DTI, and 13.7 mm (0.54 in.) monolithic Ti-6Al-4V plate. Four TPB specimens were run for each material, with the with dimension of each specimen being equal to the material thickness. The specimens had machined notches 1.3 mm (0.050 in.) deep. Fatigue precracks were grown approximately 0.25 mm (0.010 in.) in length prior to measurement of crack growth. The fatigue crack propagation tests were conducted at room temperature at 10 Hz and a R ratio of 0.1. In all laminate TPB fatigue crack propagation tests the fatigue crack was arrested at the first secondary metal interleaf that the crack encountered. Further cycling only led to delamination at the interleaf at which the crack was arrested. The laminate tests




FIGURE 44. FATIGUE CRACK PROPAGATION RATES FOR 13.2 mm (0.52 in.) THICK DIFFUSION BONDED LAMINATE DT1, CRACK DIVIDER, L-T ORIENTATION.




FIGURE 45. FATIGUE CRACK PROPAGATION RATES FOR 3.2 mm (0.12 in.) THICK TI-6A1-4V, L-T ORIENTATION.




FIGURE 46. FATIGUE CRACK PROPAGATION RATES FOR 13.7 mm (0.54 in.) THICK TI-6A1-4V, L-T ORIENTATION.




FIGURE 47. COMPARISON OF FATIGUE CRACK PROPAGATION RATES FOR MONOLITHIC TI-6A1-4V SHEET AND PLATE AND DIFFUSION BONDED LAMINATE DT1, CRACK DIV.DER, L-T ORIENTATIONS.

were continued until 100,000 cycles had been applied, and then the tests were arbitrarily stopped. Test results for these laminate specimens are given in Table 21. Typical crack growth curves for roll bonded 7475 Al/1100 Al laminate RA4 and diffusion bonded Ti-6Al-4V/6061 Al laminate DTI are given in Figures 48 and 49. Comparative tests were conducted on monolithic 7475 Al and Ti-6Al-4V. In all cases the specimens failed catastrophically within 20,000 cycles for the monolithic 7475 Al for the same applied stress intensity range [approximately 10 MPa-m^{1/2} (9 ksi-in^{1/2})]. Likewise the monolithic Ti-6Al-4V specimens failed within 30,000 cycles at the same applied stress intensity range given DTI specimens [approximately 20 MPa-m^{1/2} (18 ksi-in^{1/2})]. Photographs of comparative three point bend fatigue specimens are shown in Figure 50. These tests (combined with the results of rising load crack arrest discussed in Section 3.3.2) show that metal/metal laminates of this type possess unique crack arrest properties than can be used to great advantage in structural design for improved damage tolerance.

CRACK ARREST, L-S ORIENTATION THREE POINT BEND FATIGUE CRACK PROPAGATION TEST RESULTS FOR ROLL BONDED 7475 AI/1100 AI LAMINATE RA4 AND DIFFUSION BONDED TI-6AI-4V/6061 AI LAMINATE DTI. TABLE 21.

# CYCLES TO ARREST		2500 750 2600 1250	7800 7300 9900 8600
CRACK LENGTH AT ARREST	(in.)	(0.096) (0.096) (0.095) (0.093)	(0.130) (0.129) (0.128) (0.129)
	E E	2.44 2.44 2.41 2.41 2.36	3.30 3.28 3.25 3.28
iNITIAL CRACK LENGTH	(in.)	(9.067) (0.077) (0.064) (0.067)	(0.057) (0.060) (0.059) (0.059)
רו	mm	1.70 1.96 1.63 1.70	1.45 1.52 1.50 1.50
LOAD RANGE AP	(kips)	(6.320) (0.360) (0.320) (0.320)	(0.620) (0.620) (0.620) (0.620)
	kΝ	1.42 1.60 1.42 1.42	2.76 2.76 2.76 2.76 2.76
TEST NO.		7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	1332
PRIMARY/ Secondary Alloys		7475 A1/ 1100 A1	Ti-6A1-4v/ 6061 Al
LAMINATE PANEL DESIGNATION		RA <i>\</i> 4	DT1 (Condition A)

*R = 0.1, f = 10 Hz for all tests.




FIGURE 48. FATIGUE CRACK PROPAGATION IN 7475 A1/1100 A1 ROLL BONDED LAMINATE RA4, CRACK ARREST, L-S ORIENTATION, THREE POINT BEND SPECIMEN, - T7651 TEMPER.





FIGURE 49. FATIGUE CRACK PROPAGATION IN TI-6A1-4V/6061 A1 DIFFUSION CONDED LAMINATE DT1, CRACK ARREST, L-S CRIENTATION, THREE POINT BEND SPECIMEN; HEAT TREATMENT: CONDITION A.






FIGURE 50. THREE POINT BEND FATIGUE CRACK PROPAGATION TEST SPECIMENS: (a) CRACK ARREST AT FIRST 1100 A! INTERLEAF IN ROLL BONDED 7475 A!/1100 A! LAMINATE RA4 (TOP) AND COMPLETE FAILURE UNDER FATIGUE FOR MONOLITHIC 7475 A! (BOTTOM); (b) SAME OBSERVATIONS NOTED FOR (a) FOR DIFFUSION BONDED TI-6A!-4V/606! A! LAMINATE DT! (TOP) AND MONOLITHIC TI-6A!/4V (BOTTOM).

4.0 SUMMARY AND CONCLUSIONS

An experimental investigation of the fracture and fatigue crack propagation behavior of Al/Al and Ti/Al laminates was conducted. Seven laminate punels were fabricated using three processing methods: diffusion bonding, roll bonding, and explosive bonding. The specific laminate configurations that were fabricated and evaluated included the following alloy systems:

These laminates typically consisted of five layers of primary metal [e.g., 2.3 mm (0.090 in.) 7475 Al] interleaved with four layers of thin secondary metal [e.g., 0.13 mm (0.005 in.) 1100 Al], so that overall laminate thicknesses were approximately 11.9 mm (0.47 in.). Crack divider and crack arrest fracture toughness and fatigue crack propagation tests were conducted on these laminate panels, and the test results were compared to similar tests on sheet and monolithic plate alloys of the same strengths and chemical compositions as the primary layer alloys. The following conclusions were made from this program:

General Metal/Metal Laminate Properties

- All metal/metal laminate systems investigated showed substantially higher fracture toughness in the crack divider orientation than corresponding monolithic plate alloys.
- 2. The primary alloy single layer sheet toughness was retained in all metal/metal laminate systems evaluated. Thus, the average $K_{\rm C}$ values of the laminates were measured to be 88% to 115% of the $K_{\rm C}$ values for the single layer primary alloy sheets of approximately the same thickness as the primary layers in the laminates.

- 3. All metal/metal laminate systems tested exhibited significant capacity for crack arrest under both rising load and fatigue load conditions.
- 4. The crack divider fracture toughness of a laminate depends ultimately on the plane stress toughness of the individual primary metal layers comprising the laminates. Therefore, maximum toughness is achieved through lamination by selecting the primary metal layer thickness to correspond to that thickness at which the K_C vs. thickness relation for that single layer metal is at a maximum.
- 5. The principle requirement for attaining high fracture toughness in laminates is that the primary metal layers in a laminate be bonded together in such a way that they fail individually under plane stress conditions. The key factor controlling plane stress failure of the primary layers is is that failure occur at the primary/secondary bond prior to development of a plane strain condition through the thickness of the laminate. In metal/metal laminates, this means that the interleaf metal strength must be less than the primary metal strength. A high ductility in the interleaf metal insures that excessive delamination does not occur.
- There were no significant differences in the fatigue crack propagation rates of crack divider laminates and corresponding monolithic plate alloys.
- 7. All three fabrication processes imployed (diffusion bonding, roll bonding, and explosive bonding) were used to successfully produce highly damage tolerant laminate panels.

Al/Al Laminate Properties

- 1. Three diffusion bonded 7475 A1/1100 A1 laminates (having three different 1100 A1 interleaf thicknesses) had 50% to 56% higher critical fracture toughness values than monolithic 7475 A1 plate of the same thickness.
- 2. Measurements of diffusion profiles across 1100 Al interleaves of three different thicknesses indicated that interleaves of 0.13 mm (0.005 in.) and 0.25 mm (0.010 in.) had chemical compositions that would insure soft ductile interleaf properties. These interleaves would fail prior to development of a plane strain stress state through the thickness of the laminate. Measurements on the 0.05 mm (0.002 in.) 1100 Al interleaf

indicated excessive diffusion had occurred of principal alloying elements from the primary alloy through the 1100 Al interleaf. This interleaf thickness was concluded to be unsuitable for use in Al/Al laminate design.

- 3. The roll bonded 7475 Al/1100 Al and 7075 Al/7072 Al laminates possessed average critical fracture toughness values that were 33% and 35% higher than corresponding monolithic 7475 Al and 7075 Al plate of the same thickness.
- 4. The explosive bonded 7075 Al/7072 Al laminate had an average critical fracture toughness value that was 50% higher than monolithic 7075 Al plate of the same thickness.
- 5. Laminates having 7475 Al as the primary alloy were found to have considerably higher chack divider fracture toughness than similar laminates having 7075 Al as the primary alloy (an average of 63% for roll bonded laminates).
- 6. The single layer sheet toughness of the primary 7475 Al and 7075 Al alloys was retained in all Al/Al laminates tested.
- 7. Diffusion bonded laminates exhibited "adhesive" bondline failures. Roll bonded laminates showed a combination of "adhesive" and "cohesive" interleaf failure. The explosive bonded laminate displayed 100% "cohesive", ductile interleaf failure. "Cohesive" interleaf failure is considered the preferable failure mode for efficient metal/metal laminate design.

Ti/Al Laminate Properties

- 1. The diffusion bonded Ti-6Al-4V/6061 Al laminate possessed an average critical fracture toughness that was 117% higher than the baseline monolithic Ti-6Al-4V alloy plate of the same thickness.
- Laminate primary/secondary bondline failures were observed to be "adhesive" in character.
- 3. The single layer fracture toughness of the primary Ti-6Al-4V alloy was essentially retained in the Ti/Al laminate panel. The average $K_{\rm C}$ value for the laminate was only 12% less than that for single layer Ti-6Al-4V sheet of the same thickness as the primary titanium layers in the laminate.

REFERENCES

- 1. H. L. Leichter, "Impact Fracture Toughness and Other Properties of Brazed Metallic Laminates," J. Spacecraft 7(3), 1113 (1966).
- J. D. Embury, N. J. Petch, A. E. Wraith, and E. S. Wright, "The Fracture of Mild Steel Laminates," Trans. AIME 239, 114 (1967).

THE REAL PROPERTY OF THE PROPERTY OF THE PARTY OF THE PAR

- 3. J. G. Kaufman, "Fracture Toughness of 7075-T6 and -T651 Sheet, Plate, and Multilayered Adhesive-Bonded Panels," J. Basic Engr., Trans. ASME, 89, Series D (3), 503 (1967).
- 4. R. F. McCartney, R. C. Richard, and P. S. Trozzo, "Fracture Behavior of Ultrahigh-Strength-Steel Laminar Composites," <u>Trans. ASM</u> 60, 384 (1967).
- 5. E. A. Almond, N. J. Petch, A. E. Wraith, and E. S. Wright, "The Fracture of Pressurized Laminated Cylinders", J. Iron Steel Inst. 207, 1319 (1969).
- 6. E. A. Almond, J. D. Embury, and E. S. Wright, "Fracture in Laminated Materials," <u>Interfaces in Composites</u>, ASTM STP 452 (American Society for Testing and Materials, Phila.), 107 (1969).
- 7. S. D. Antolovich, K. Kasi, and G. R. Chanani, "Fracture Toughness of Duplex Structures: Part II Laminates in the Divider Orientation," Fracture Toughness, Proceedings of the 1971 National Symposium on Fracture Mechanics, Part II, ASTM STP 514 (American Society for Testing and Materials, Phila.), 135 (1972).
- 8. D. Cox and A. S. Tetelman, <u>Improved Fracture Toughness of Ti-6A1-4V</u>
 <u>Through Controlled Diffusion Bonding</u>, Air Force Materials Laboratory
 <u>Technical Rept. AFML-TR-71-264</u>, (1972).
- 9. D. O. Cox and A. S. Tetelman, <u>Fracture Toughness and Fatigue Properties</u> of Titanium Laminate Composites Produced by Controlled Diffusion Bonding, Air Force Materials Laboratory Technical Rept. AFML-TR-73-288, (1973).
- 10. S. D. Antolovich, G. R. Chanani, A. Saxena, and I. C. Wang, "Fracture Mechanism Transitions in Laminate Composites," J. Phys. D: Appl. Phys. 6, 560 (1973)
- 11. A. A. Anctil, R. Chait, C. H. Curll, and E. B. Kula, <u>Structural Properties</u> of <u>Dual Hardness Steel Armor</u>, Army Materials and Mechanics Research Center Technical Rept. AMMRC TR 73-6, (1973).
- 12. E. B. Kula, A. A. Anctil, and H. H. Johnson, <u>Fatigue Crack Growth in Dual-Hardness Steel Armor</u>, Army Materials and Mechanics Research Center Technical Rept. AMMRC TR 74-6, (1974).
- 13. N. G. Ohlson, "Fracture Toughness of Laminated Steels", Eng. Fract. Mech. 6, (#3), 459 (1974).
- 14. T. M. Devine, S. F. Floreen, and H. W. Hayden, "Fracture Mechanisms in Maraging Steel-Iron Laminates", <u>Eng. Fract. Mech. 6</u> (#2), 315 (1974).

- 15. S. Floreen, N. Kenyon, and H. W. Hayden, "The Fabricability and Toughness of Laminar Composites of Maraging Steel", <u>Trans. ASME</u>, <u>J. Engr. Mater. Tech. Vol. 95</u>, <u>Series H (#3)</u>, 176 (1974).
- 16. J. R. Ellis and G. E. kuhn, <u>Adhesively Bonded Multi-Layer F-104 Aft Fuselage Ring Fitting</u>, Air Force Materials Laboratory and Air Force Flight Dynamics Laboratory Technical Rept. AFML-TR-74-158 and AFFDL-TR-74-105, (1974).
- 17. J. F. Throop and J. F. Miller, <u>Fatigue Behavior of Metal Laminates</u>, Watervliet Arsenal Technical Rept. WVT-TR-75035, (1975).
- 18. P. T. Lum, R. Chait, and C. F. Hickey, Jr., "The Toughness of High Hardness Laminar Composite Steel as Influenced by Specimen and Crack Orientation," Met. Trans. 6A, 1093 (1975).
- 19. J. A. Alic, "Stable Crack Growth in Adhesively Bonded Aluminum Alloy Laminates," <u>Internl. J. Fracture 11</u> (#4), 701 (1975).
- 20. R. R. Wells, Low-Temperature Large-Area Brazing of Titanium Structures, Air Force Materials Laboratory Technical Report AFML-TR-75-50, (1975).
- 27. S. J. Acquaviva and R. Chait, "The Effect of a Rising Tensile Load on Crack Extension in a Laminar Composite Steel," Met. Trans. 7A, 1595 (1976).
- 22. "Plane-Strain Fracture Toughness of Metallic Materials," American Society for Testing and Materials Standard Test Method E399-74.
- 23. <u>Damage Tolerant Design Handbook</u> (Metals and Ceramics Information Center, Battelle Columbus Laboratories, Columbus, Ohio), (1975).
- 24. D. M. Fisher, R. T. Bubsey, and J. E. Srawley, <u>Design and Use of Displacement Gage for Crack-Extension Measurements</u>, National Aeronautics and Space Administration Technical Note NASA TN D-3724, (1966).
- 25. W. F. Brown, Jr. and J. E. Srawley, <u>Plane Strain Crack Toughness Testing</u> of High Strength Metallic Materials, <u>ASTM STP 410</u> (American Society for Testing and Materials, thila.), (1966).
- 26. B. Gross and J. E. Srawley, <u>Stress-Intensity Factors for Three-Point Bend Specimens by Boundary Collocation</u>, National Aeronautics and Space Administration Technical Note NASA TN D-3092, (1965).
- 27. "Proposed Method of Test for Fatigue Crack Growth Rates Above 10⁻⁷ In./ Cycle," American Society for Testing and Materials, ASTM Task Group E24.04.01 on Fatigue Crack Growth Rate Testing, unpublished preliminary method, (1976).

- 28. J. C. Newman, Jr., "Stress Analysis of the Compact Tension Specimen Including the Effects of Pin Loading, "Fracture Analysis, Proceedings of the 1973 National Symposium on Fracture Mechanics, Part II, ASTM STP 560 (American Society for Testing and Materials, Phila.), 105 (1974).
- 29. J. E. Srawley, <u>Wide Range Stress Intensity Factor Expressions for ASTM E 399 Standard Fracture Toughness Specimens</u>, National Aeronautics and Space Administration Technical Memorandum NASA TM X-71881, (1976).
- 30. F. L. Mehr, Alcoa 7475 Sheet and Plate, Aluminum Co. of America, Alcoa Green Letter 216 (2nd Rev.), (1973).
- 31. J. G. Kaufman, Fracture Toughness Testing, Including Screening and Quality Control Testing, in the Aluminum Industry, Alcoa Research Laboratories Rept. No. 9-72-18 (Presented at the 1972 Wester Conference, Los Angeles), (1972).
- 32. R. R. Wells, "New Alloys for Advanced Metallic Fighter-Wing Structures", Presented at AIAA/ASME/SAE 15th Structures, Structural Dynamics and Materials Conference, Las Vegas, Nevada, April 17-19, 1974, AIAA Paper No. 74-372, (1974).

DISTRIBUTION LIST

Department of the Navy Naval Air Systems Command Washington, D. C. 20361 Attn: Mr. W. T. Highberger AIR-52031D (10 cys)

Department of the Navy Sea Systems Command Washington, D. C. 20361 Attn: Code 03423

Chief of Naval Research Department of the Navy Washington, D. C. 20361 Attn: ONR 423, 471 (2 cys)

Director
U.S. Naval Research Laboratory
Metallurgy Division
Washington, D. C. 20390

Commanding Officer
Naval Air Development Center,
Johnsville
Aero Materials Laboratory
Warminster, Pennsylvania 18974
Attn: Mr. F. S. Williams

Air Force Materials Laboratory Wright-Patterson Air Force Base Dayton, Ohio 45433 Attn: Codes LLM, LC, MXE, MBC & LLS (1 each)

U. S. Energy Research and Development Administration Division of Reactor R&D Washington, D. C. 20545 Attn: Mr. J. M. Simmons, Chief Metallurgy Section

Army Research Office
Box CM, Duke Station
Durham, North Carolina 27706
Attn: Metallurgy and Ceramics
Division

Department of the Interior Bureau of Mines Washington, D. C. 20240

U. S. Department of Commerce National Bureau of Standards Washington, D. C. 20234

National Academy of Sciences National Materials Advisory Board 2101 Constitution Avenue Washington, D. C. 20418 Attn: Dr. J. C. Lane

National Aeronautics and Space ·
Administration
600 Independence Avenue
Washington, D. C. 20546

U. S. Army Materials & Mechanics Research Center Watertown Arsenal Watertown, Massachusetts 02172 Attn: Mr. S. Arnold

Commander
U. S. Army Munitions Command
Frankford Arsenal
Pitman Dunn Laboratory
Philadelphia, Pennsylvania 19137
Attn: Mr. K. Kleppinger

Battelle Memorial Institute Defense Metals Information Center 505 King Avenue Columbus, Ohio 43201

Avco Space Systems Division Lowell Industrial Park Lowell, Massachusetts 01851

Brush Wellman, Inc. 17876 St. Clair Avenue Cleveland, Ohio 44110 Attn: Mr. Bryce King The Boeing Company Aerospace Division P. O. Box 3707 Seattle, Washington 98124 Attn: Mr. E. C. Bovee

Dr. D. P. Ames McDonnell Douglas Research Labs St. Louis, Missouri 63166

Defense Documentation Center Cameron Station Bldg. 5 Alexandria, Virginia 22314 Attn: TISTA (14 cys) Via: Naval Air Syst ns Command Code AIR-954 Washington, D. C. 20361

Gould, Inc. Gould Information Center 540 East 105th Street Cleveland, Ohio 44108

The Franklin Institute Research
Laboratories
Twentieth & Parkway
Philadelphia, Pennsylvania 19103
Attn: Technical Director

Dr. John A. Schey Department of Mechanical Engr. University of Waterloo Waterloo, Ontario Canada N2L 3G1

Convair Division General Dynamics San Diego, California 92112 Attn: Mr. A. Hurlich

Dr. Charles Gilmore
School of Engineering and
Applied Science
George Washington University
Washington, D. C. 20006

ITT Research Institute 10 West 35th Street Chicago, Illinois 60616 Attn: Dr. N. Parikh Kawecki Berylco Industries P. O. Box 1462 Reading, Pennsylvania 19603 Attn: Dr. J. P. Penny

Ladish Company Packard Avenue Cudahy, Wisconsin 53110 Attn: Mr. Joseph Picher Librarian

Linde Company Division of Union Carbide P. O. Box 44 Tonawanda, New York 14152

Lockheed Aircraft Corporation Lockheed Missile Systems Division P. O. Box 501 - Orgn. 80-72, Bldg. 18 Sunnyvale, California 91088 Attn: Dr. M. I. Jacobson

Lycoming Division Avco Corporation 550 South Main Street Stratford, Connecticut 06497 Attn: Division Library

Midwest Research Institute 425 Volker Boulevard Kansas City, Missouri 64110

Northrup Norair 3901 West Broadway Hawthorne, California 90250 Attn: Technical Information 3343-32

Solar Division International Harvester Company 2200 Pacific Highway San Diego, California 92112 Attn: Dr. A. G. Metcalfe

TRW Inc., Jet & Ordnance Division 23555 Euclid Avenue Cleveland, Ohio 44117 Attn: Elizabeth Barrett United Aircraft Research Laboratory East Hartford, Connecticut 06108 Attn: Mr. Roy Fanti

Vought Corporation P. O. Box 5907 Dallas, Texas 75222

Dr. Paul Lowenstein Nuclear Metals, Inc. 2229 Main Street Concord, Massachusetts 01742

General Electric
Missile & Space Division
Materials Science Section
P. O. Box 8555
Philadelphia, Pennsylvania 91901

Reynolds Metals Company Reynolds Metals Building Richmond, Virginia 23218 Attn: Technical Library

Artech Corporation 28!6 Fallfax Drive Falls Church, Virginia 22042 Attn: Mr. Henry Hahn

Massachusetts Institute of Technology
Department of Metallurgy and Material
Science
Cambridge, Massachusetts 02139
Attn: Dr. W. A. Backofen

Attn: Dr. W. A. Backofen Dr. N. J. Grant (1 each)

General Electric Research Laboratory Schenectady, New York 12301 Attn: Dr. Don Wood Mr. David Lillie (1 each)

Dr. Gary Geschwind Plant 26 (Research Dept.) Grumman Aerospace Corporation Bethpage, N. Y. 11714

Aluminum Company of America 1200 Ring Bldg. Washington, D. C. 20036 Attn: Mr. G. B. Barthold Pratt & Whitney Aircraft Corp. 400 Main Street East Hartford, Connecticut 06108

Department of Metallurgical
Engineering
Drexel University
32nd & Chestnut Streets
Philadelphia, Pennsylvania 19104

Commonwealth Scientific 500 Pendleton Street Alexandria, Virginia 22314 Attn: Mr. A. P. Divecha

Dr. Howard Bomberger Reactive Metals, Inc. Niles, Ohio 44446

Mr. W. Spurr The Boeing Company 12842 72nd Avenue, N. E. Kirkland, Washington 98033

Commander
Naval Air Systems Command
Representative
Atlantic
Naval Air Station
Norfolk, Virginia 23511

Commander
Naval Air Systems Command
Representative
Pacific
Naval Air Station, North Island
San Deigo, California 92135

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Naval Air Station
Alameda, California 94501

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Marine Corps Air Station
Cherry Point, North Carolina 28533

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Naval Air Station
Jacksonville, Florida 32212

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Bldg, 604
Naval Air Station
Pensacola, Florida 32508

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Naval Air Station, North Island
San Diego, California 92135

Commanding Officer
Naval Air Rework Facility
(Code 34100)
Naval Air Station
Norfolk, Virginia 23511

Defense Advanced Research Project Agency 1400 Wilson Boulevard Arlington, Virginia 22209 Attn: Dr. E. C. Van Reuth

Rockwell International Science Center P. O. Box 1082 Camino Dos Rios Thousand Oaks, California 91320

Pratt & Whitney Aircraft
Division of United Aircraft Corp.
Florida R&D Center
P. O. Box 2691
West Palm Beach, Florida 33402

Lockheed Missiles & Space Company, Inc.
Palo Alto Research Laboratory
3251 Hanover Street
Palo Alto, California 94304
Attn: Dr. Thomas E. Tietz
52-31/204

Titanium Metals Corporation of America
Henderson, Nevada 89015
Attn: Dr. Harry W. Rosenberg

Southwest Research Institute 8500 Culebra Road P. O. Drawer 28510 San Antonio, Yexas 78284 Attn: Dr. C. Gerald Cardner

Grumman Aerospace Corporation Bethpage, L. I., New York 11714 Attn: Mr. R. Heitzmann (2 cys)

Mr. George Hsu Manager of Industry Standards Reynolds Metals Corp. 6601 W. Broad Street Richmond, Virginia 23261

McDonnell Aircraft Co. St. Louis, Missouri 63166 Attn: Mr. H. C. Turner

Dr. John K. Tien Henry Krumb School of Mines Columbia University New York, New York 10027

Dr. J. C. Williams
Department of Netallurgy and
Materials Science
Carnegie-Mellon University
Pittsburgh, Pennsylvania 15213

Boeing Vertol Company Boeing Center P. O. Box 16858 Philadelphia, Pennsylvania 19142

Rockwell International Los Angeles Division International Airport Los Angeles, California 90009

Lockheed Aircraft
P. O. Box 551
Burbank, CA 91520
Attn: Mr. George G. Wald
Dept. 75-74, Bldg. 63, Plant A-1

Douglas Aircraft Company 3855 Lakewood Boulevard Long Beach, CA 50846 Alcoa Technical Center Alcoa Center, Pa. 15069 Attn: Mr. A. N. Anderson

United Aircraft Corporation Sikorsky Aircraft Division Stratford, CT 06497

Hughes Aircraft Company Aerospace Group Culver City, CA 90230

Bell Helicopter Company P. 0. Box 482 Fort Worth, TX 76101

Army Aviation Systems Command Attn: AMSAV-ERE P. O. Box 209 St. Louis, MO 63166

E. F. Industries 1301 Courtesy Road Louisville, Colorado 80027

Mr. J. F. Dolowy, Jr. DWA Composite Specialties, Inc. 21119 Superior St. Chatsworth, California 91311

Dr. B. B. Rath Code 6490 U. S. Naval Research Laboratory Material Sciences Division Washington, D. C. 20340

Dr. O. D. Sherby
Department of Materials Science and
Engineering
Stanford University
Stanford, California 94305

Battelle Columbus Laboratories 505 King Avenue Columbus, Ohio 43201 Attn: Mr. H. E. Pattee